



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72336
Promised Date:
07 JUN 25



WO #: 72336 (Appointment Date: 08 SEP 2025 - Time: 10:45am)

Customer Name: 60002 - BARELA JR,
FRANK

Completed Date: 27 FEB 26

Invoice#:

Author: BRIAN

Stock Desc: 9431 2025 OPEN RANGE
22MLS

Serial#: 58TBM0BM1S7543053

Date In: 08 SEP 25

Chassis#: 58TBM0BM1S7543053

Time In:

Miles/Hrs:

Tag#: 6749

Purchased Date: 24 JUN 25

Warranty Date: 24 JUN 25

Job #0 - External

CLAIM: J01465295

Labor

Job #	Description	Total
0	DIAGNOSIS	N/C
Subtotal for Job #0:		0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES SLIDEOUT IS NOT OPENING EVENINLY ITS BINDING

CAUSE: Not moving out in sync the rear has about 1/4 catch up both in and out
The rear slide rails are badly damaged and screws have been broken off and bent
See measurement sheet
Slide control voltage 14.24 dev

CORRECTION: Replace both upper and lower slide rails on the rear
Recanted slide room and sync the motors
And continue diagnostic
Added new photos
Plugged unit into shore power
Ran side out half way
Removed all screws from the rail
Supported the side
Removed all screws from the h column
Remove both front and rear schwintec rails
Installed new system front and rear
Set the front to 2 1/2 inches
Set the rear to 2 1/2 inches
Reattached all rails and h column
Tested slide
Slide is working within tolerance
Work completed

Labor

Job #	Description	Total
1	SLIDE OUT DIAGNOSE	537.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 60002
BARELA JR, FRANK



0340903 SCHWINTEK MECHANISM, SLIDE 1.00 989.23 989.23
OUT 2 MOTOR 300:1

Subtotal for Job #1: 1,526.23

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES DRIVERS SIDE ROOF IS LEAKING TOWARDS THE FRONT -
SWEEPER MOLDING ON SLIDE IS FOLDED INWARDS.

CAUSE: Front side slide seals have some adhesive on them and are flipping back and forth properly
Top slide seal is folded in the middle standing straight up and on the front top corner has been torn away
not over lapping the side seal

CORRECTION: Recommend replacing the top seal and both side seals
Removed top bubble seal and wiper seal
Installed ew wiper seal and bubble seal
Work completed

Labor

Job #	Description	Total
2	SLIDE OUT SEALS	358.00

Subtotal for Job #2: 358.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES AWNING IS LEAKING BETWEEN THE UNIT AND THE AWNING

CAUSE: Leaking between awning and side of the unit

CORRECTION: Checked while awning was closed from the roof and under
Opened the awning and checked from the roof and under
Did not find any signs of a leak
Scraped an area where the putty was coming out on top near the roof edge and sealed the length of the
unit with silicone
Job completed
.50HRS

Labor

Job #	Description	Total
3	AWNING TOP ADJUST	89.50

Subtotal for Job #3: 89.50

Job #3-1 - Internal

COMPLAINT: TWO VALANCES

CAUSE: Not installed

CORRECTION: Installed new valances on both windows at the kitchen sink
The blind to the right had to lowered in order for the valance to fit
Work completed

Labor

Job #	Description	Total
3-1	INSTALL VALANCES	N/C

Parts

Part #	Description	Qty	Price	Total
3904019.WALOX	VALANCE - 29.25" X 3" X 4.5" BOX	1.00	N/C	N/C
	WALLACE ONYX			
3904020.WALOX	VALANCE - 35.25" X 3" X 4.5" BOX	1.00	N/C	N/C
	WALLACE ONYX			

W/O: 72336
Promised Date: 27 JUN 25



Customer #: 60002
BARELA JR, FRANK



Subtotal for Job #3-1: 0.00

Job #4 - Internal

COMPLAINT: CUSTOMER STATES FRONT DRIVERS SIDE JACK IS BENT

CAUSE: Bent at the top at the attachment point to the frame

CORRECTION: Replace the jack

Removed 5 self tapping screws took bent jack off unit

Put new jack in place using the same screws fastened the new jack back to the frame work completed

Labor

Job #	Description	Total
4	BALANCING JACK	N/C

Parts

Part #	Description	Qty	Price	Total
0218770	JACK, STABILIZER 24" 5000# TRISTAR	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES WATER HEATER, POPS THE BRAKER AND STARTS SMOKING WHEN YOU TURN THE SWITCH ON.

CAUSE: Water did not work on electric

CORRECTION: During the diagnostic for the water heater on electric

I found as soon as the switch was turned it blew the monitor fuse

Tested the 120 side which tested correctly

Tested the amps at 10.34 which is correct

Further testing it was found the signal wire was connected to the ground and ground was connected to the brown wire

Once the wires were switched the fuse stopped blowing and the water heater began working.

Allowed the electric to run until it produced hot which it did.

Tested the water heater on the gas side and was working correctly

Water heater repaired job complete

5.00HRS

Labor

Job #	Description	Total
5	WATER HEATER DIAGNOSE	895.00

Parts

Part #	Description	Qty	Price	Total
1703	ATC-15 FUSE	1.00	0.34	0.34

Subtotal for Job #5: 895.34

Job #6 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES ON DRIVERS SIDE THERE IS A LINE ON THE SLIDE HANGING DOWN , CUSTOMER BELEIVES IT'S A GAS LINE

CAUSE: Gas line for slide out not secure

CORRECTION: Moved gas line up and zip tied it to the electric cable bundle moved slide in and out now is secure and not hanging down

Job completed

.25HRS

Labor

Job #	Description	Total
6	LP PRESSURE HOSE	44.75

W/O: 72336
Promised Date: 27 JUN 25



Customer #: 60002
BARELA JR, FRANK



Subtotal for Job #6: 44.75

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize rv basic

CORRECTION: Completed

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total: 989.57

Labour Total: 1,924.25

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 2,913.82

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

****MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND****

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 27 Feb 2026

W/O: 72336
Promised Date: 27 JUN 25



Customer #: 60002
BARELA JR, FRANK

