



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72414-1
Promised Date:
01 MAR 26



WO #: 72414-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 04 MAR 26

Invoice#:

Author: ADVISOR

Stock Desc: 9613 2026 OPEN RANGE

COLT 22MDS

Serial#: 6G3055

Chassis#: 58TBM0BM6T76G3055

Date In: 17 JAN 26

Time In:

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Job #2 - Warranty

COMPLAINT: White sealant all over the slide wiper seals

CAUSE: White sealant on slide wiper seals

CORRECTION: Used a cleaner and removed the sealant from both wiper slide seals on both sides
Work completed .15

Labor

Job #	Description	Total
2	WIPER SEALS	17.90
Subtotal for Job #2:		17.90

Job #3 - Internal

COMPLAINT: Grey tank dump handle missing

CAUSE: Handle missing

CORRECTION: Replaced handle with new one threaded handle .10

Labor

Job #	Description	Total
3	DUMP HANDLE	N/C

Parts

Part #	Description	Qty	Price	Total
11-0583	BLADEX METAL HANDLE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Transferred to RV*72414-2 on 04 MAR 26

Estimate amount was 0.00

Drawer next to the oven second one down appears to warped not closing on right side

CAUSE: Rail misaligned drawer latch not screwed to drawer

Customer #: 1000
MYERS "RV" CENTER,
INC.,





CORRECTION: Found the bottom of the drawer was loose staples pulled out
 Found the drawer latch was not connected
 Found right drawer rail was not straight
 Attached the latch with 2 screws
 Stapled the drawer bottom back in place
 Pulled the staples from the drawer rail moved it inward and screwed it back in place
 Drawer works correctly
 Work complete .20

Labor		
Job #	Description	Total
4	MULTIPLE LABOR CODES	0.00
Subtotal for Job #4:		0.00

Job #5 - Warranty

COMPLAINT: Slide trim far left side fell off

CAUSE: Trim fell off

CORRECTION: Nailed both trim pieces back in place used white putty to fill new nail holes
 Work completed .15

Labor		
Job #	Description	Total
5	SLIDE TRIM	17.90
Subtotal for Job #5:		17.90

Job #6 - Warranty

COMPLAINT: Transferred to RV*72414-2 on 04 MAR 26
 Estimate amount was 0.00
 Wall for the bathroom pocket door is warped rubbing the paint off the door

CAUSE: Warped wall

CORRECTION: See new photos

Labor		
Job #	Description	Total
6	BATHROOM POCKET DOOR	0.00
Subtotal for Job #6:		0.00

Job #7 - Warranty

COMPLAINT: Transferred to RV*72414-2 on 04 MAR 26
 Estimate amount was 0.00
 Wall next to the bed entry door side has a gouge in it will need to replace whole panel

CAUSE: Gouge in wall

CORRECTION: Recommend replacement of the panel
 New photos attached

Labor		
Job #	Description	Total
7	GOUGE NEXT TO ENTRY DOOR	0.00
Subtotal for Job #7:		0.00

Job #8 - Warranty

COMPLAINT: Drawer under the refrigerator does not latch

CAUSE: Drawer not latching



CORRECTION: Moved the catch forward about 1/8 of an inch drawer now latches .10

Labor		
Job #	Description	Total
8	DRAWER	17.90
Subtotal for Job #8:		17.90

Job #9 - Warranty

COMPLAINT: Bare wire hanging out of the side range hood will need to remove hood and find out where the wire needs to be connected

CAUSE: Found a wire sticking out from under the range hood

CORRECTION: Took the four screws out found the wire was just laying there no connection
Screwed hood back in place
Work completed .15

Labor		
Job #	Description	Total
9	WIRE AT RANGE HOOD	17.90
Subtotal for Job #9:		17.90

Job #10 - Warranty

COMPLAINT: Bare staples in ceiling need to putty filled

CAUSE: No putty

CORRECTION: Found two bare staples in the ceiling
Used white putty and filled the holes work completed .10

Labor		
Job #	Description	Total
10	STAPLES IN CEILING	17.90
Subtotal for Job #10:		17.90

Job #11 - Warranty

COMPLAINT: Black tank flush leaking water in under belly

CAUSE: Leaking water coming out in the underbelly

CORRECTION: Took 6 screws out of the underbelly
Pulled the underbelly down hooked up water to verify where the water was coming from
Could not see leaks on the line in the underbelly
Checked inside the unit and could feel water spraying in the wall
Removed the flush valve and found the water line nut was cross threaded and not in all the way
Unscrewed the water and reconnected it correctly
Tested with water again and leak stopped
Screwed the flush valve back to the side of the unit
Screwed the underbelly back in place
Work complete .50

Labor		
Job #	Description	Total
11	BLACK TANK FLUSH	17.90
Subtotal for Job #11:		17.90

W/O: 72414-1
Promised Date: 04 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72414-1
Promised Date: 04 MAR 26

Parts Total:	0.00
Labour Total:	107.40
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	107.40

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 04 Mar 2026

Customer Signature : _____



Customer #: 1000
MYERS "RV" CENTER,
INC.,

