



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72596
Promised Date:
13 MAR 26



WO #: 72596 (Appointment Date: 23 OCT 2025 - Time: 03:15pm)
Customer Name: 42735 - TIDWELL, DONALD RAY
Completed Date: 11 MAR 26
Invoice#:
Author: ADVISOR
Stock Desc: 9477 2025 OPEN RANGE
3X 390TBS
Serial#: 58TCM0BV6S3B63147 Date In: 23 OCT 25
Chassis#: 58TCM0BV6S3B63147 Time In:
Miles/Hrs:
Tag#: 7122
Purchased Date: 25 MAR 25
Warranty Date: 25 MAR 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES FLOORING TO THE LEFT OF FRONT ENTRY DOOR IS BUBBLED

CAUSE: Floorbis bubbling near entry door.see pictures

CORRECTION: Lino will have to be peeled back to lay down adhesive and roll bubbles out.

Labor

Job #	Description	Total
1	VINYL FLOORING DIAGNOSE	179.00
Subtotal for Job #1:		179.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES FLOORING BY THE LADDER TO THE BUNK IS BUBBLING

CAUSE: Floor is bubbling near bunk ladder.see pictures
Bubbling floor by bunk beds ladder

CORRECTION: Lino will have to be peeled back to lay adhesive down and roll bubbles out.
Completely cleaned the floor , located the bubble
Found spot that would not be noticeable
Injected dicor adhesive under the linoleum
Used a large roller and spread the glue around the area of the bubbling
Ensured the injection hole was closed
Used plywood and weight to hold the flooring in place will allow it to set over night
Work completed

Labor

Job #	Description	Total
2	VINYL FLOORING DIAGNOSE	179.00
Subtotal for Job #2:		179.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES PANTRY HAS COME OFF THE TRACKS

CAUSE: Pantry door rail ball bearing strip has fallen out of track needs to be replaced.
Drawer guide broke and fell apart

Customer #: 42735
TIDWELL, DONALD RAY





CORRECTION: Remove and replace door rail. Waiting on part.
 Removed the drawer
 Unscrewed the top drawer from the top on the drawer and installed new rail
 Removed top inside rail and installed new rail
 Unscrewed bottom rail from the drawer and installed new rail
 Unscrewed inside rail and installed new rail
 Checked drawer operation
 Found the the drawer was closing correctly with the top closed against the magnet there was a 1/2 inch gap at the bottom
 Removed drawer adjust the top rail from the support trim up to a level position
 Added a shim to the back of the bottom rail
 Checked the drawer operation the drawer now closes evenly top and bottom
 Work completed

Labor		
Job #	Description	Total
3	PANTRY DOOR	17.90

Parts				
Part #	Description	Qty	Price	Total
0339304	DRAWER GUIDE 18" CABINET SIDE 35MM 75# BALL BEARING	1.00	7.87	7.87
0339305	DRAWER GUIDE 18" DRAWER SIDE 35MM 75# BB	1.00	2.64	2.64

Subtotal for Job #3: 28.41

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES MASTER BED IS NOT FOLDING WHEN PULLING SLIDE IN

CAUSE: Bed will extend but no retract due to gear box is damaged.
 Bed power arm not raising bed up

CORRECTION: Remove and replace retracting arm and gesr box.
 Part on order.
 Removed mattress
 Removed 10 screws from plywood and removed plywood
 Pulled the cotter pins and released the arm
 Disconnected the power and took the arm out
 Put new arm in place and attached it at the head of the bed, connected the power , extended it to meet the foot of the bed and attached
 Tested the movement with the plywood or mattress
 Worked correctly
 Installed the plywood with the 10 screws
 Put the mattress back in place
 Tested the movement again worked correctly
 Work completed

Labor		
Job #	Description	Total
4	BED DIAGNOSE	89.50

Parts				
Part #	Description	Qty	Price	Total
2078088	ACTUATOR, BED LIFT 24" STROKE 400LBS 12V	1.00	467.01	467.01

Subtotal for Job #4: 556.51

Job #5 - Warranty

COMPLAINT: Transferred to RV*72596-1 on 04 MAR 26
 Estimate amount was 0.00
 CUSTOMER STATED MAIN AWNING HINGE BOLT SNAGGED A WIRE AND PULLED WIRES LOOSE
 CUSTOMER STATES THE WHITE PLASTIC WIRE COVER IS ON THE KITCHEN COUNTER NEAR THE SINK





CAUSE: Awning wire was pulled out by arm bolt causing wire cover to come off.

CORRECTION: Inspected wires for damage and reinstalled wire cover with a small bead of clear silicone to hold in place.

Labor		
Job #	Description	Total
5	AWNING WIRING DIAGNOSE	0.00
Subtotal for Job #5:		0.00

Job #6 - Internal

COMPLAINT: CUSTOMER STATES SLIDE ON DRIVERS SIDE LOOKS TO HAVE SEAL COMING OUT

CAUSE: Inspected seals on all slideouts.

CORRECTION: All seals are in great conditions.

Labor		
Job #	Description	Total
6	SLIDE OUT ROOM DIAGNOSTIC TIME	N/C
Subtotal for Job #6:		0.00

Job #7 - Internal

COMPLAINT: CUSTOMER STATES HOOK UP FOR THE ICE MAKER BLEW - CUST. CONNECTED BUT WOULD LIKE IT CHECKED

CAUSE: Inspected water line around and inside frig.
 Ice maker line leak recheck

CORRECTION: Water line is secured with tape from customer.
 Inspected the water as goes under the cabinet and under the sink everything appears to be correct
 Can not inspect behind the refrigerator without pulling the fridge
 Work complete
 Checked the connection behind the refrigerator from the outside and it is tight and appears to be correct

Labor		
Job #	Description	Total
7	ICE MAKER COMPRESSOR CONNECTOR REPAIR LEAK	N/C
Subtotal for Job #7:		0.00

Job #8 - Internal

COMPLAINT: Transferred to RV*72596-2 on 11 MAR 26

Estimate amount was 0.00

CUSTOMER STATES FRONT PASS. JACK HAS PAINT OR SOME KIND OF OVERSPRAY ON IT & WILL NOT GO DOWN WITH OUT HELP

CAUSE: Cycled jack several times without any problems. Checked all wire connections.
 Jack operation and paint over spray

CORRECTION: Do not duplicate problem.
 Ran the jack up and down and auto level jacks worked correctly
 Cleaned as much of the paint over spray as possible
 Work completed
 Found on the manual part of the jack leg passenger side there was a heavy coat of paint over spray
 Cleaned the paint over spray off lubricated the leg and moved it up and down numerous times works much easier

Labor		
Job #	Description	Total
8	JACK	N/C



Subtotal for Job #8: 0.00

Job #NOTE - External
CUSTOMER STATES UNIT IS WINTERIZED

Labor		Total
Job #	Description	N/C
NOTE	DIAGNOSIS	

Subtotal for Job #NOTE: 0.00

Parts Total: 477.52
Labour Total: 465.40
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 942.92

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 11 Mar 2026

W/O: 72596
Promised Date: 13 MAR 26



Customer #: 42735
TIDWELL, DONALD RAY

