



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72342  
 Promised Date:  
 SEP 25



WO #: 72342 (Appointment Date: 09 SEP 2025 - Time: 10:15am)  
 Customer Name: 60565 - MANUEL, PAULA V  
 Completed Date:  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9547 2026 TRACER 255DS  
 Serial#: 5ZT2TRRB0TB526225  
 Chassis#: 5ZT2TRRB0TB526225  
 Miles/Hrs:  
 Tag#: 6980  
 Purchased Date: 23 AUG 25  
 Warranty Date: 23 AUG 25  
 Date In: 09 SEP 25  
 Time In:

**Job #1 - Internal**

COMPLAINT: CUSTOMER WOULD LIKE THE STOCK NUMBER REMOVED FROM THE TONGUE JACK - A-FRAME

CAUSE: Stock numbers on A frame

CORRECTION: Removed numbers. Job complete

**Labor**

Job #	Description	Total
1	REMOVE STOCK # A-FRAME	N/C
<b>Subtotal for Job #1:</b>		<b>0.00</b>

**Job #2 - Internal**

COMPLAINT: CUSTOMER STATES WHEN YOU FLUSH THE TOLIET WATER COMES OUT THE FRONT OF THE BOWL EVEN ON LOW WATER PRESSURE

CAUSE: 1 of 3 flushes the water runs out of the toilet bowl.

CORRECTION: Working as designed. Up to manufacture for solution.

**Labor**

Job #	Description	Total
2	TOILET BOWL	N/C
<b>Subtotal for Job #2:</b>		<b>0.00</b>

**Job #3 - Warranty**

COMPLAINT: CUSTOMER STATES THE PANEL UNDER THE BATHROOM SINK IS NOT SECURED

CAUSE: Panel is coming loose due to faulty staples.

CORRECTION: Removed and added new staples to secure panel. Job complete  
 .20HRS

**Labor**

Job #	Description	Total
3	PANEL, INTERIOR	28.50

Customer #: 60565  
 MANUEL, PAULA V



Subtotal for Job #3: 28.50

**Job #4 - Warranty**

COMPLAINT: CUSTOMER STATES THE METAL BLIND OVER THE OVEN DOES NOT HAVE AN ADJUSTMENT ROD

CAUSE: Blind rod missing.

CORRECTION: Replaced blind rod. Job complete .10HRS

**Labor**

Job #	Description	Total
4	BLIND WAND	19.00

**Parts**

Part #	Description	Qty	Price	Total
20-1151	12" MINI BLIND WAND	1.00	2.83	2.83

Subtotal for Job #4: 21.83

**Job #5 - Warranty**

COMPLAINT: CUSTOMER STATES BOTH BEDROOM CLOSETS HAVE LIGHT COMING THRU ON THE BOTTOM

CAUSE: Light coming thru bottom caused by gaps in walls.

CORRECTION: Removed trim and added a silicone to seal gaps in wall. Reinstalled trims. Job complete 1.00HRS

**Labor**

Job #	Description	Total
5	CLOSET (2)	190.00

Subtotal for Job #5: 190.00

**Job #6 - Warranty**

COMPLAINT: JOB ADDED: WHEN ENTERING THE UNIT THE SEAL TO THE RIGHT OF THE SLIDE HAS LIGHT COMING IN

CAUSE: Seal halfway through bends up not laying flat as rest of seal.

CORRECTION: Remove and replace slide seal. Part needs to be ordered.

\*\*Request 2HR's\*\*

**Labor**

Job #	Description	Total
6	SLIDE OUT SEAL	95.00

Subtotal for Job #6: 95.00

**Job #7 - Internal**

COMPLAINT: THE WINDOW OVER THE COUCH THE LOCK IS REVERSED FROM THE OTHER LOCKS

CAUSE: Window latch cannot be reversed will not work.

CORRECTION: Window lock is working as intended. Job complete

**Labor**

Job #	Description	Total
7	WINDOW LATCH/LOCK	N/C

W/O: 72342  
Promised Date: 05 DEC 25



Customer #: 60565  
MANUEL, PAULA V



Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: JOB ADDED: AROUND THE BATHROOM DOOR THE STORAGE ROOM DOOR AND THE LOCKS THE MOLDING IS COMING OFF

CAUSE: Several areas of trim covering coming off. Will need several sticks of trim to replace. Doors will also need to be replaced with new door handles.

CORRECTION: Remove and replace damaged trim. Remove & Replace 2 doors with handles. Parts need to be ordered.

1.50HRS

**Labor**

Job #	Description	Total
8	MOLDING	228.00

Subtotal for Job #8: 228.00

**Job #9 - Warranty**

COMPLAINT: JOB ADDED: THE MOLDING IN FRONT OF THE COUCH TO THE LEFT, ON THE FLOOR IS COMING OFF

CAUSE: Wall trim is peeling near couch. See pictures

CORRECTION: Remove and replace trim. Parts need to be ordered. .25HRS

**Labor**

Job #	Description	Total
9	MOLDING R&R	47.50

Subtotal for Job #9: 47.50

**Job #10 - Warranty**

COMPLAINT: JOB ADDED: WHEN ENTERING THE UNIT, TO THE RIGHT OF THE COUCH THE PANEL IS CRACKED & SCRATCHED

CAUSE: Wall panel near couch is damaged has cracks. Order new panel piece. See pictures

CORRECTION: Remove couch to access panel remove all trim remove panel.cut new piece to proper size and install.Install all trim and move couch back into place.waiting on parts. PER BRANDY NEED THE WOOD GRAIN WALL PANEL 2.00HRS

**Labor**

Job #	Description	Total
10	PANEL, INTERIOR (PER SQ.FT), R & R	190.00

Subtotal for Job #10: 190.00

**Job #11 - Warranty**

COMPLAINT: JOB ADDED: THE BOTTOM DRAWER TO THE RIGHT OF THE STOVE WILL NOT STAY CLOSED

CAUSE: Drawer rails sre out of alignment does not close flush. See pictures

CORRECTION: Realigned drawer rails for proper operation. Job complete .20HRS

W/O: 72342  
Promised Date: 05 DEC 25



Customer #: 60565  
MANUEL, PAULA V



W/O: 72342  
Promised Date: 05 DEC 25

<b>Labor</b>		
Job #	Description	Total
11	CABINET DRAWER ADJUST	38.00
<b>Subtotal for Job #11:</b>		<b>38.00</b>

**Job #12 - Internal**  
 COMPLAINT: JOB ADDED: DRAIN TANKS & BLOW OUT LINES

CAUSE: Blow out lines and drain tanks.

CORRECTION: Blewed out lines and drained tanks.

<b>Labor</b>		
Job #	Description	Total
12	WINTERIZE RV - BASIC	N/C
<b>Subtotal for Job #12:</b>		<b>0.00</b>

Parts Total: 2.83  
 Labour Total: 836.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 838.83**

NOTICE:  
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : \_\_\_\_\_

Date: 28 Jan 2026



Customer #: 60565  
 MANUEL, PAULA V

