

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2563934
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRRB0TB526225
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT255DS
PAULA MANUEL		DEALER RO #	72342
1316 MONTERREY RD NE		CLAIM START DATE	01/28/2026
Rio Rancho, NM 87144		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	08/23/2025	WARRANTY EXPIRATION DATE	08/23/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:33:28 :: Complaint: Customer states the panel under the bathroom sink is not secured Cause: Panel is coming loose due to faulty staples Correction: Removed and added new staples to secure panel			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$38.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-99-01-00-001014	Mini-Blind or Vertical Patio Blind Wand - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:35:19 :: Complaint: Customer states metal blind over the oven does not have an adjustment rod Cause: Blind rod is missing Correction: Replace blind rod			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$19.00
Serial#		Appr Hrs	0.10	Appr Labor Amt \$19.00
	Notes			
	NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor

Line# 3	Operation Code	Operational Description		
	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:37:05 :: Complaint: Customer states both bedroom closets have light coming through on the bottom Cause: Light coming through bottom is caused by gaps in the walls Correction: Removed trim and added silicone to seal gaps in the wall. Reinstalled trims.			
Model#		Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00
Serial#		Appr Hrs	1.00	Appr Labor Amt \$190.00
	Notes			
	Pictures are needed for futher consideration.TD Picture added NVCB,Because of the size of the gaps to R&R panels and seal 1 hour. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

