

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2563934
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRRB0TB526225
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT255DS
PAULA MANUEL		DEALER RO #	72342
1316 MONTERREY RD NE		CLAIM START DATE	01/28/2026
Rio Rancho, NM 87144		CLAIM END DATE	02/25/2026
USA			
Retail Date of Purchase	08/23/2025	WARRANTY EXPIRATION DATE	08/23/2026

Claim Line Details

Labor

Line# 1

Operation Code	30-102-12-00-002691	Operational Description
		Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:33:28 :: Complaint: Customer states the panel under the bathroom sink is not secured Cause: Panel is coming loose due to faulty staples Correction: Removed and added new staples to secure panel		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$38.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$38.00
Notes		

Part

Line# 1

Item #	USERPART	Description
		Staples
Model #		Serial #
Sub Qty	1.00	Sub Dlr Price
		\$1.90
Appr Qty	1.00	Sub Freight
		\$0.00
		Part tag
		Appr Price
		\$1.90
		Appr Freight
		\$0.00
Notes		

Labor

Line# 2

Operation Code	30-99-01-00-001014	Operational Description
		Mini-Blind or Vertical Patio Blind Wand - Interior/Soft Goods/Replace/No Tread Code
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:35:19 :: Complaint: Customer states metal blind over the oven does not have an adjustment rod Cause: Blind rod is missing Correction: Replace blind rod		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$19.00
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$19.00
Notes		
NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD		

Part

Line# 1

Item #	30I42148A	Description
		WAND , ALUMINUM BLINDS , 12" WAND , ALUMINUM BLINDS , 12", (MFG# WAND), 9475
Model #		Serial #
Sub Qty	1.00	Sub Dlr Price
		\$3.25
		Sub Freight
		\$0.00
		Part tag

Appr Qty 1.00 Appr Dlr Price \$0.39 Appr Freight \$0.00

Notes

Dealer has submitted a part cost higher than what is allowed according to the Forest River Off-the-Shelf (OTS) Parts Policy. The approved cost has been adjusted to: Dealer cost \$0.25 + state allowed mark-up of 15% for NM + OTS part allowance of 35%. In the future, please use the OTS calculator at the bottom of the policy to determine the amount Forest River will pay for the part.

Labor

Line# 3

Operation Code 30-102-24-00-001094 Operational Description Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:37:05 :: Complaint: Customer states both bedroom closets have light coming through on the bottom Cause: Light coming through bottom is caused by gaps in the walls Correction: Removed trim and added silicone to seal gaps in the wall. Reinstalled trims.

Model# Dlr Sub Hrs 1.00 Sub Labor Amt \$190.00

Serial# Appr Hrs 1.00 Appr Labor Amt \$190.00

Notes

Pictures are needed for futher consideration.TD
Picture added
NVCB,Because of the size of the gaps to R&R panels and seal 1 hour. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1

Item # Description Part tag
USERPART Silicone
Model # Serial # Sub Freight \$0.00
Sub Qty 1.00 Sub Dlr Price \$9.50 Appr Freight \$0.00
Appr Qty 1.00 Appr Dlr Price \$9.50

Notes

Labor

Line# 4

Operation Code 20-56-01-00-000599 Operational Description Slide Out T-Molding - Exterior/Slide Out System-Seals, Exterior Room/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:39:47 :: Complaint: When entering the unit the seal to the right of the slide has light coming in Cause: Seal halfway through bends up and is not laying flat like the rest of the seal Correction: Remove and replace slide seal

Model# Dlr Sub Hrs 2.00 Sub Labor Amt \$380.00

Serial# Appr Hrs 1.00 Appr Labor Amt \$190.00

Notes

NVCB,Flat rate is .5 I will go 1 hour.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1

Item # Description Part tag
F100483995 SEAL, WIPE W/ TALL, SINGLE BULB, FLIP 'N SEAL, 2" (750' PER BOX) SIDE, 04002739
Model # Serial # Sub Freight \$17.07
Sub Qty 8.00 Sub Dlr Price \$19.28 Appr Freight \$17.07
Appr Qty 8.00 Appr Dlr Price \$19.28

Notes

Labor

Line# 5

Operation Code 30-101-01-00-001076 Operational Description Hinged Passage Door - Interior/Interior Doors/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:42:18 :: Complaint: Around the bathroom door the storage room door and the locks the molding is coming off Cause: Several areas of trim covering are coming off. Will need several sticks of trim to replace. Doors will also need to be replaced with new door handles.

Correction: Remove and replace damaged trim, remove and replace 2 doors with handles.

Model# Dlr Sub Hrs 1.50 Sub Labor Amt \$285.00

Serial# Appr Hrs 1.50 Appr Labor Amt \$285.00

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1	Item #	Description	Serial #	Part tag
	F100124396	DOOR KNOB, LEVER STYLE, MATTE BLACK, 1226-MB		
	Model #			
	Sub Qty 1.00	Sub Dlr Price \$12.71		Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$12.71		Appr Freight \$0.00

Notes

Line# 2	Item #	Description	Serial #	Part tag
	F100686065	DOOR, PASSAGE, 22" X 74", IZZY GRANITE, 625084		
	Model #			
	Sub Qty 1.00	Sub Dlr Price \$54.29		Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$54.29		Appr Freight \$0.00

Notes

Line# 3	Item #	Description	Serial #	Part tag
	F100721936	DOOR, PASSAGE, 23-7/8" X 74", IZZY GRANITE, 625091		
	Model #			
	Sub Qty 1.00	Sub Dlr Price \$54.57		Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$54.57		Appr Freight \$0.00

Notes

Line# 4	Item #	Description	Serial #	Part tag
	USERPART	Putty, trim sticks		
	Model #			
	Sub Qty 1.00	Sub Dlr Price \$14.25		Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$14.25		Appr Freight \$0.00

Notes

Labor

Line# 6	Operation Code	Operational Description
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:45:31 :: Complaint: The molding in front of the couch to the left on the floor is coming off Cause: Wall trim is peeling near the couch Correction: Remove and replace trim

Model# Dlr Sub Hrs 0.25 Sub Labor Amt \$47.50

Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 7	Operation Code	Operational Description
	30-102-01-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-28 12:47:13 :: Complaint: When entering the unit to the right of the couch the panel is cracked and scratched Cause: Wall panel near the couch is damaged and has cracks. Correction: Remove couch to access panel, remove all trim, remove panel cut new piece to proper size

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.