



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72581
 Promised Date:
 06 JAN 26



WO #: 72581
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9631 2026 AVENGER
 16RBX
 Serial#: 815404
 Chassis#: 5ZT2AVECXTG815404
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 17 DEC 25
 Time In:

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pdi travel trailer

CORRECTION: Pdi complete

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize rv basic

CORRECTION: Work completed

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





Job #01 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Decal bubbling
 Black strip passenger side front top

CORRECTION: Decal is bubbling
 Recommend removal of the old decal and replace with new one
 Request .50hr

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #01: 0.00

Job #02 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Decal bubbling
 Drivers rear large.black decal bubbling

CORRECTION: Recommend the removal of the old decal which will involve the removal of the drivers side corner molding and vinyl insert, cleaning off silicone
 Installing new decal , reinstalling corner mold and vinyl insert and resealing with clear silicone
 Requesting 1.0 hour

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #02: 0.00

Job #03 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Decal coming apart and coming off

CORRECTION: Recommend the replacement of the whole front forest river letter decal
 Will require the removal of the old decal cleaning the surface and installing the new decal
 Requesting 30 minutes

Labor

Job #	Description	Total
03	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #03: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 07 Jan 2026

Customer Signature : _____

Customer Work Order

W/O: 72581
Promised Date: 06 JAN 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

