

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Paid CLAIM 2543554 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2AVECXTG815404 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 452 / 452 ITEM # AVT16RBX-452 DEALER RO # 72581 CLAIM START DATE 01/07/2026 CLAIM END DATE 02/25/2026
--	--

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** 20-43-01-00-000589 **Operational Description** Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:05:33 :: Complaint: Black strip on passenger side front top is bubbling Cause: Decal is bubbling Correction: Recommend removal of bubbled decal and replacement with a new one

Model#	Dlr Sub Hrs 0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$19.00

Notes
 NVCB,Time requested is excessive ,decal does not need replaced,Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. air bubbles can be removed by pricking with knife or needle and smoothing out.TD

Labor

Line# 2 **Operation Code** 20-43-01-00-000589 **Operational Description** Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:07:11 :: Complaint: Drivers rear large black decal is bubbling Cause: Decal is bubbled Correction: Recommend the removal of the old decal which will involve the removal of the drivers side corner molding and vinyl insert, clean off silicone, install new decal, reinstall corner molding and vinyl insert and reseal

Model#	Dlr Sub Hrs 1.00	Sub Labor Amt \$190.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$19.00

Notes
 NVCB,Time requested is excessive.Decal does not need replaced, air bubble can be removed by pricking it a knife or needle and smooth out.Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 3 **Operation Code** 20-43-01-00-000589 **Operational Description** Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:08:38 :: Complaint: Decal is coming apart and coming off Cause: Decal is coming off/apart Correction: Recommend the repalcement of the whole front forest river letter decal. Will require removal of old decal, clean the surface and install new decal

Model#	Dlr Sub Hrs 0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs 0.50	Appr Labor Amt \$95.00

