



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72583-1
Promised Date:
20 JAN 26



WO #: 72583-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9633 2026 AVENGER
16RBX
Serial#: 815409
Chassis#: 5ZT2AVEC9TG815409
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 24 JAN 26
Time In:

Job #01 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Decals bubbling right rear black

CORRECTION: Recommend removal and replacement of decal
Corner trim and vinyl insert will have to be removed
Old decal removed and area cleaned
Install new decal
Reinstall corner mold and vinyl insert and silicone the edge
Request 1 hour

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #01:		0.00

Job #02 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Right front black stripe decal bubbling

CORRECTION: Recommend removal and replacement of the decal cleaning area installing new decal
Request 30 minutes

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #02:		0.00

Job #03 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Left front top black stripe decal bubbling

CORRECTION: Recommend removal and replacement of decal .
Remove old decal clean area install new decal
Request 30 minutes

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72583-1
Promised Date: 28 JAN 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Labor		
Job #	Description	Total
03	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #03:		0.00

Job #04 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Left rear black decal bubbling

CORRECTION: Recommend removal and replacement of decal
Will have to remove corner mold and vinyl insert
Remove old decal and silicone
Clean area
Install new decal
Reinstall corner mold and vinyl insert res silicone edge
Request 1 hour

Labor		
Job #	Description	Total
04	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #04:		0.00

Job #05 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Bathroom sink stopper missing

CORRECTION: Order new sink stopper

Labor		
Job #	Description	Total
05	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #05:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 24 Jan 2026

