



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72750
 Promised Date:
 06 DEC 25



WO #: 72750 (Appointment Date: 06 DEC 2025 - Time: 09:15am)
 Customer Name: 60035 - TAFOYA, ABEL LARRY Completed Date:
 Invoice#: 307772
 Author: ADVISOR
 Stock Desc: 9419 2025 AVENGER
 28BHS
 Serial#: 5ZT2AVTB1SB938658 Date In: 06 DEC 25
 Chassis#: 5ZT2AVTB1SB938658 Time In:
 Miles/Hrs:
 Tag#: 7026
 Purchased Date: 07 JUN 25
 Warranty Date: 07 JUN 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES PASS. SIDE PANEL WALL, INSIDE, HAS SEPARATED. AS SOON AS YOU ENTER THRU REAR DOOR IT WILL BE TO THE LEFT... ***WILL NEED MEASUREMENTS***

CAUSE: Panel came loose from the wall and is torn

CORRECTION: Found the panel on the wall at the steps for the bunk beds has come loose from the wall and and is torn

Recommend full replacement of the panel

In order to complete this job it will require the removal of the steps to the bunk beds and the closet at the top of the steps, which will involve removing the batten strips along all edges, the inside corner trim along the ceiling. Removing the damaged panel, installing the new panel, reinstalling the closet and steps.

Installing all trim and putting the nail and staple holes

Requesting 5 hours to complete this job

Will need 1 4x8 sheet of paneling

1 plastic seam trim that goes between paneling seams, 1 batten strip matching the paneling, 1 inside corner molding lights brown color, 1 light brown batten strip the matches the steps and closet.

Labor

Job #	Description	Total
1	PANEL, INTERIOR	28.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 28.50

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES END TABLES ON EACH SIDE OF BED HAVE GAPS CAUSING A DRAFT OF AIR

CAUSE: Gab between side of the master bed and exterior wall allowing air to come from the basement under the bed

CORRECTION: Checked the edges and there is light coming through between the exterior wall and bed edges

Sealed the edge all the way around the bed with clear silicone

Work completed

Note the whole master bed is on top of the front basement

Customer #: 60035
 TAFOYA, ABEL LARRY





Labor		
Job #	Description	Total
2	CABINET SHELF REPAIR (2)	95.00
Subtotal for Job #2:		95.00

Job #3 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES, INSIDE SHOWER TOP WALL IS COMING APARTS = WHEN YOU WALK IN THE SHOWER IT WILL BE ON THE LEFT SIDE

CAUSE: Shower wall loose at the top on the short ends

CORRECTION: Found the shower wall was loose on the short ends.
 At the top I added 3 push buttons to each side by drilling holes through the shower wall and wall pressing the buttons in and securing the shower wall back in place.
 Then used clear silicone across the top of the whole shower to seal it and prevent any water from getting between the walls.
 Work complete

Labor		
Job #	Description	Total
3	PANEL, SHOWER	47.50
Subtotal for Job #3:		47.50

Job #4 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES BY REAR DOOR, TO THE RIGHT AT THE J-WRAP A SCREW IS MISSING

CAUSE: Screw fell out of the j wrap

CORRECTION: Replaced the missing screw with a new one
 Checked all screws all the way around the unit to make sure they are all secure
 Work complete

Labor		
Job #	Description	Total
4	J-WRAP SCREW	19.00
Subtotal for Job #4:		19.00

Job #5 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES THE PANEL TO THE RIGHT, BY WINDOW & BEFORE BATHROOM, IS LOOSE

CAUSE: Panel came loose

CORRECTION: Found the panel between the wipe down in the hall way came loose
 Stapled panel back to the stud and used putty to cover the staple holes

Labor		
Job #	Description	Total
5	PANEL, INTERIOR	47.50

Parts				
Part #	Description	Qty	Price	Total
8112	CHRISTMAS TREE CLIP	6.00	0.05	0.30
Subtotal for Job #5:				47.80

Job #6 - External

COMPLAINT: CUSTOMER PURCHASED ANTIFREEZE

CAUSE: Customer purchase



CORRECTION: Customer purchase

Labor			Total
Job #	Description		N/C
6	DIAGNOSIS		N/C

Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	1.00	N/C	N/C

Subtotal for Job #6: 0.00

Job #NOTE - External

COMPLAINT: CUSTOMER STATES UNIT IS NOT WINTERIZED BUT HAS ALL LINES DRAINED

CAUSE: Customer will do the work

CORRECTION: Customer will winterize himself

Labor			Total
Job #	Description		N/C
NOTE	DIAGNOSIS		N/C

Subtotal for Job #NOTE: 0.00

Parts Total: 0.30
 Labour Total: 237.50
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 237.80

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 15 Dec 2025

W/O: 72750
Promised Date: 13 DEC 25



Customer #: 60035
TAFOYA, ABEL LARRY

