

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2563630
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSVB4SG128261
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF295BHS
LAURA LICCIONE		DEALER RO #	72842
3310 ICARIAN CT NE		CLAIM START DATE	01/28/2026
Rio Rancho, NM 87124		CLAIM END DATE	02/19/2026
USA			
Retail Date of Purchase	01/17/2026	WARRANTY EXPIRATION DATE	01/17/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-99-01-00-001018	Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 10:42:22 :: Complaint: Blind next to the sofa will not go up Cause: Blind in the dinette area to the right does not work, will not roll up Correction: Took blind down and rolled up by hand, pulled it down and locked again and will not go up. Recommend replacement.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00	
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00	
	Notes			
	The time requested is excessive for this repair, time adjusted. VCB .20 to R&R the blind due to it not working properly. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp. Need picture of entire shade per flat rate notes Picture added			

Part

Line# 1	Item #	Description			
	F100274638	SHADE, ROLLER, 26" X 32" BLACK, FRNB26X32RS49NDV			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$44.97	Sub Freight	\$40.63	
	Appr Qty 1.00	Appr Dlr Price \$44.97	Appr Freight	\$40.63	
	Notes				

Labor

Line# 2	Operation Code	Operational Description		
	20-70-19-00-000715	Access Door - Exterior/Access Doors/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 10:44:19 :: Complaint: Access panel for slide wiring is loose Cause: Access panel loose, only one screw and it is bent Correction: Set access panel in place and added a screw to each side of the access panel Additional Note : stephanie@dealer-advisors.com, 2026-01-28 10:46:21 :: Could not find exact flat rate code, chose a close one			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00	
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00	
	Notes			

Part

Line# 1	Item #	Description
	USERPART	Screws

