

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS Paid	
MYERS RV CENTER INC		CLAIM 2583788	
12024 CENTRAL AVE S.E.		CLAIM ORIGIN WEB	
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC5TG815374
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16BHX-452
DANIEL RICE		DEALER RO #	72874
10413 MANZANILLO AVE NE		CLAIM START DATE	02/18/2026
Albuquerque, NM 87111		CLAIM END DATE	02/23/2026
USA			
Retail Date of Purchase	01/02/2026	WARRANTY EXPIRATION DATE	01/02/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-66-02-00-000687	Screen Door Latch - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-18 09:54:30 :: Complaint: Customer states entry door handle is loose Cause: Door handle is loose due to screws on the hinge side not fully tightened Correction: Tightened the screws and rechecked, doors work correctly			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00
	Notes			

Labor

Line# 2	Operation Code 20-78-12-00-003681	Operational Description Awning Arm, each - Exterior/Awnings (Lippert)/Resecure or Tighten/No Tread Code		
Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-02-18 09:58:37 :: Complaint: Rear awning arm is not retracting all the way and is loose Cause: Tested the awning in and out and found the rear arm was hanging up at full close. Found the gib screws were not holding the fabric in place. Correction: Realigned the fabric, add new gib screws and test. Awning now closes properly.				
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
Notes NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD				

Part

Line# 1	Item # USERPART	Description Screws			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$2.85	Sub Freight \$0.00		
	Appr Qty 1.00	Appr Dlr Price \$2.85	Appr Freight \$0.00		
	Notes				

Labor

Line# 3	Operation Code	Operational Description
	20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
	Complaint, Cause, Correction	
	Original Note : stephanie@dealer-advisors.com, 2026-02-18 10:02:54 :: Complaint: Dead bolt will not lock Cause:	

Dead bolt is not locking Correction: Locked the dead bolt a dozen times and seemed to work better after multiple uses. Dead bolt is working.

Model#

Serial#

Notes

Dlr Sub Hrs

Appr Hrs

0.20

0.20

Sub Labor Amt \$38.00

Appr Labor Amt \$38.00

Submitted	Labor Amt	\$133.00	Approved	Labor Amt	\$133.00
	Parts & Freight	\$2.85		Parts & Freight	\$2.85
	Total	\$135.85		Total	\$135.85

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.