

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2615334
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2LC0B3TB012590
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048A
OWNER INFORMATION		ITEM #	LCT3510DB
BERRETT HARRISON		DEALER RO #	73028-1
4848 DODGE AVE NW		CLAIM START DATE	03/20/2026
Albuquerque, NM 87114		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/19/2026	WARRANTY EXPIRATION DATE	03/19/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-138-01-00-001525	Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:02:15 :: Complaint: Rear grey tank handle is missing Cause: Handle is missing Correction: Replace handle and thread in place			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-100-24-00-001051	Cabinet - complete - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:04:36 :: Complaint: Rear medicine cabinet face fell off Cause: not properly secured Correction: Remove entire cabinet from the wall, taking out 4 screws. Removed door from cabinet taking out 4 screws. Removed side panel. took out the screws holding the face in place. Installed new screws that were slightly longer. Face is now secure. Reinstalled cabinet to the wall and reinstall the door.			
Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$66.50
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes			
	Excessive labor requested. Reduced to a more reasonable rate			

Labor

Line# 3	Operation Code	Operational Description		
	30-100-24-00-003310	Cabinet Drawer - Box - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:09:55 :: Complaint: Drawer in the front bathroom will not close Cause: Cables are sticking up behind the drawer Correction: Rolled cables up and drawer now closes			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
Notes				

Labor

Line# 4	Operation Code	Operational Description
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction	

Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:12:52 :: Complaint: Huge gaps between wall and closet floor in front bedroom, both closets. Cause: Loose panel at closet floor. Found that it was not attached to the frame near the wall. Correction: Used screws to attach panel to the metal frame. Used white silicone on the under side to seal it.

Model# Dlr Sub Hrs 0.35 Sub Labor Amt \$66.50

Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

Excessive labor requested. Reduced to a more reasonable rate.

Labor

Line# 5

Operation Code

30-100-12-00-001049

Operational Description

Cabinet End Panel - Interior/Cabinetry/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:14:42 :: Complaint: Panel under kitchen sink fell off Cause: Panel broke off base plate Correction: Removed three screws and stapled panel back to base plate and reinstall panel

Model# Dlr Sub Hrs 0.15 Sub Labor Amt \$28.50

Serial# Appr Hrs 0.10 Appr Labor Amt \$19.00

Notes

Excessive labor requested. Reduced to a more reasonable rate

Labor

Line# 6

Operation Code

40-196-24-11-001297

Operational Description

Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:19:25 :: Complaint: Water heater has a short, it is blowing fuses and will not turn on Cause: Began at water heater and replace the fuse and it blew right away. Checked wiring diagram at water heater and showed it was correct. Went to the back of the water heater and showed correct. Went to the controller. Removed controlled and tested it. Found positive wire was on the negative and the negative was on the positive. Correction: Cut the wires and switched the wires. Reconnected with clamp type wire nuts. Controller came on right away. Started tested of the water heater at the sink next to the controller. Found the sink was plumbed backwards. Sink repair will be on a separate line.

Model# Dlr Sub Hrs 1.00 Sub Labor Amt \$190.00

Serial# Appr Hrs 0.70 Appr Labor Amt \$133.00

Notes

Excessive labor requested. Reduced to a more reasonable rate

Labor

Line# 7

Operation Code

60-139-24-00-001556

Operational Description

Galley Sink - Plumbing/Kitchen (Galley) Sink/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-03-20 09:23:31 :: Complaint: During repair for water heater issue, we had began testing and found that the sink was plumbed backwards. Cause: Installed incorrectly Correction: Switch the plumbing on the sink

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00

Serial# Appr Hrs 0.50 Appr Labor Amt \$95.00

Notes

Submitted

Labor Amt \$484.50
Parts & Freight \$0.00
Total \$484.50

Approved

Labor Amt \$361.00
Parts & Freight \$0.00
Total \$361.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.