



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72188
 Promised Date:
 20 AUG 25



WO #: 72188
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9591 2026 R-POD RP-185
 Serial#: 035153
 Chassis#: 4X4TRPU19TB035153
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 11 AUG 25
 Time In:

Job #0 - Internal
 PICS FOR ALL JOBS

Labor

Job #	Description	Total
0	PICTURES	N/C
Subtotal for Job #0:		0.00

Job #1 - Internal
 Transferred to RV*72188-1 on 21 NOV 25
 Estimate amount was 0.00
 CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty
 COMPLAINT: Entry door will not close
 CAUSE: Installed incorrectly

CORRECTION: Move striker plate a quarter of an inch to allow for proper operation
 .20HRS

Labor

Job #	Description	Total
2	ENTRY DOOR ADJUST	38.00
Subtotal for Job #2:		38.00

Job #3 - Internal
 COMPLAINT: Spare tire holder loose

CAUSE: U BOLT BROKE FROM BEING OVERTIGHTENED AND MISALIGNED

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



CORRECTION: REMOVE AND REPLACE SPARE TIRE HOLDER
.30HRS

Labor

Job #	Description	Total
3	SPARE TIRE HOLDER	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Water leak at rear of unit in underbelly

CAUSE: Incorrect installation

CORRECTION: During inspection water was leaking on ground when conducting flood test. Checked connections at shower , sink, and faucets. Removed access cover under all fixtures and performed leak test to ensure no pressure side leak present . Noted toilet level dropping . Inspected toilet seal but no leak noted.

Remove and install underbelly from rear bumper to Axle had to remove propane quick connect and metal clamps. Removed foam and reseal underbelly 3.4hrs

1st attempt repair using liquid beutle . Had to pull unit out of bay to dump water out to allow adhesive to cure. Flood tested for 15 minutes and unit still leaked 1.8hrs

2nd attempt repair using abs glue. Pulled unit out and dumped and allowed tank to dry. Removed tank flush and cleaned both surfaces. Applied abs glue and secured tank flush to base . Let cure and flood tested to ensure repair. Unit passed leak test. 3.2
8.00HRS

Labor

Job #	Description	Total
4	WATER SYSTEM PUMP DIAGNOSE	1,140.00

Parts

Part #	Description	Qty	Price	Total
06-7828	BUTYL RUBBER SEALANT - 10.1OZ TUBE (GRAY)	1.00	6.33	6.33

Subtotal for Job #4: 1,146.33

Job #5 - Warranty

COMPLAINT: Water pump turns on no pressure

CAUSE: Incorrect installation

CORRECTION: Winterize valave had loose clamps. Installed new clamps and tested. System functioning as designed
.50HRS

Labor

Job #	Description	Total
5	WATER PUMP	57.00

Subtotal for Job #5: 57.00

Job #6 - Warranty

COMPLAINT: Black tank flush vacuum breaker leaking

CAUSE: Loose connection

CORRECTION: Tightened connections and re tested
.50HRS

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Labor		
Job #	Description	Total
6	BLACK TANK FLUSH	95.00
Subtotal for Job #6:		95.00

Job #7 - Warranty

COMPLAINT: Poor water pressure went on city hook up

CAUSE: Debris in fresh water system.

CORRECTION: Pulled all airaitor and removed debris. Flushed system until no debris noted.
 .20HRS

Labor		
Job #	Description	Total
7	CITY WATER PRESSURE	57.00

Parts				
Part #	Description	Qty	Price	Total
38-8522	TEFLON THREAD SEAL	1.00	0.40	0.40
Subtotal for Job #7:				57.40

Job #8 - Warranty

COMPLAINT: Door side rear stabilizer jack bent

CAUSE: DEFECTIVE JACK

CORRECTION: REMOVE AND REPLACE JACK
 .20HRS

Labor		
Job #	Description	Total
8	STABILIZER	1.90

Subtotal for Job #8: 1.90

Job #9 - Warranty

COMPLAINT: SPARE TIRE CARRIER U-BOLT IS BROKEN

CAUSE: OVERTIGHTENED

CORRECTION: REMOVE AND REPLACE U BOLT
 .20HRS

Labor		
Job #	Description	Total
9	SPARE TIRE CARRIER	0.00

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: FRONT SHADE LOWER BRACKET IS BROKEN

CAUSE: DEFECTIVE BRACKETS

CORRECTION: REPLACE BRACKETS
 .20HRS

Labor		
Job #	Description	Total
10	SHADE BRACKETS	0.00



Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: L/S COMPARTMENT PANEL IS UNATTACHED

CAUSE: NOT SECURED PROPERLY

CORRECTION: REMOVE PANEL AND REMOVE STAPLES. REINSTALL AND RESTAPLE PANEL PROPERLY .50HRS

Labor

Job #	Description	Total
11	PANEL	0.00

Subtotal for Job #11: 0.00

Job #PDI1 - Internal

Transferred to RV*72188-1 on 21 NOV 25

Estimate amount was 0.00

PRE-PDI NEW TT - 3.0

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Parts Total: 6.73
Labour Total: 1,388.90
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 1,395.63

NOTICE: DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 14 Jan 2026

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,

