



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72188
 Promised Date:
 20 AUG 25



WO #: 72188
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9591 2026 R-POD RP-185
 Serial#: 035153
 Chassis#: 4X4TRPU19TB035153
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 11 AUG 25
 Time In:

Job #0 - Internal
 PICS FOR ALL JOBS

Labor

| Job # | Description | Total |
|-----------------------------|-------------|-------------|
| 0 | PICTURES | N/C |
| Subtotal for Job #0: | | 0.00 |

Job #1 - Internal
 Transferred to RV*72188-1 on 21 NOV 25
 Estimate amount was 0.00
 CHECK IN NEW UNIT

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 1 | DIAGNOSIS | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|-----------------------------|--------------------------|------|-------|-------------|
| SS-I | SHOP SUPPLIES - INTERNAL | 0.00 | N/C | N/C |
| Subtotal for Job #1: | | | | 0.00 |

Job #2 - Warranty
 COMPLAINT: Entry door will not close
 CAUSE: Installed incorrectly

CORRECTION: Move striker plate a quarter of an inch to allow for proper operation
 .20HRS

Labor

| Job # | Description | Total |
|-----------------------------|-------------------|-------------|
| 2 | ENTRY DOOR ADJUST | N/C |
| Subtotal for Job #2: | | 0.00 |

Job #3 - Internal
 COMPLAINT: Spare tire holder broken
 CAUSE: UNKNOWN

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



CORRECTION: NEED TO ORDER

Labor

| Job # | Description | Total |
|-------|-------------------|-------|
| 3 | SPARE TIRE HOLDER | N/C |

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Water leak at rear of unit in underbelly

CAUSE: Incorrect installation

CORRECTION: Had to gain access to black tank flush. Removed rear portion of underbelly from bumper to rear of axle. Removed sewer, spout, Support, propane, lines, and propane quick disconnect. Removed tank flush from tank cleaned both surfaces attempted to use similar product as manufacturer liquid beaultle Decor brand. Product did not hold flood test. Removed tank flush, clean surface and used ABS glue secured tank flesh and flooded system. No leaks noted.
8.00HRS

Labor

| Job # | Description | Total |
|-------|----------------------------|-------|
| 4 | WATER SYSTEM PUMP DIAGNOSE | N/C |

Parts

| Part # | Description | Qty | Price | Total |
|---------|---|------|-------|-------|
| 06-7828 | BUTYL RUBBER SEALANT - 10.1OZ TUBE (GRAY) | 1.00 | N/C | N/C |

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: Water pump turns on no pressure

CAUSE: Incorrect installation

CORRECTION: Winterize valave had loose clamps. Installed new clamps and tested. System functioning as designed
.50HRS

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 5 | WATER PUMP | N/C |

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: Black tank flush vacuum breaker leaking

CAUSE: Loose connection

CORRECTION: Tightened connections and re tested
.50HRS

Labor

| Job # | Description | Total |
|-------|------------------|-------|
| 6 | BLACK TANK FLUSH | N/C |

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: Poor water pressure went on city hook up

CAUSE: Debris in fresh water system.

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,



CORRECTION: Pulled all airator and removed debris. Flushed system until no debris noted.
.20HRS

Labor

| Job # | Description | Total |
|-------|---------------------|-------|
| 7 | CITY WATER PRESSURE | N/C |

Parts

| Part # | Description | Qty | Price | Total |
|---------|--------------------|------|-------|-------|
| 38-8522 | TEFLON THREAD SEAL | 1.00 | N/C | N/C |

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: Door side rear stabilizer jack bent

CAUSE: DEFECTIVE JACK

CORRECTION: REMOVE AND REPLACE JACK

.20HRS

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 8 | STABILIZER | N/C |

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: SPARE TIRE CARRIER U-BOLT IS BROKEN

CAUSE: OVERTIGHTENED

CORRECTION: REMOVE AND REPLACE U BOLT

.20HRS

Labor

| Job # | Description | Total |
|-------|--------------------|-------|
| 9 | SPARE TIRE CARRIER | N/C |

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: FRONT SHADE LOWER BRACKET IS BROKEN

CAUSE: DEFECTIVE BRACKETS

CORRECTION: REPLACE BRACKETS

.20HRS

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: L/S COMPARTMENT PANEL IS UNATTACHED

CAUSE: NOT SECURED PROPERLY

CORRECTION: REMOVE PANEL AND REMOVE STAPLES. REINSTALL AND RESTAPLE PANEL PROPERLY

.50HRS

Subtotal for Job #11: 0.00

Job #PDI1 - Internal

Transferred to RV*72188-1 on 21 NOV 25

Estimate amount was 0.00

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,



| Labor | | | Total |
|--------------|--------------------|--|-------|
| Job # | Description | | N/C |
| PDI1 | PDI TRAVEL TRAILER | | N/C |

| Other Services | | | | |
|-----------------------|---------------|------|-------|-------|
| Code | Description | Qty | Price | Total |
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |

Subtotal for Job #PDI1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Dec 2025



Customer #: 1000
MYERS "RV" CENTER,
INC.,

