



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72188
Promised Date:
NE MAB 26



WO #: 72188

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9591 2026 R-POD RP-185
Serial#: 035153
Chassis#: 4X4TRPU19TB035153
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 11 AUG 25
Time In:

Job #0 - Internal

CLAIMS: 2449382 / 2551396
PICS FOR ALL JOBS

Labor

Job #	Description	Total
0	PICTURES	N/C
Subtotal for Job #0:		0.00

Job #1 - Internal

Transferred to RV*72188-1 on 21 NOV 25
Estimate amount was 0.00
CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: Entry door will not close

CAUSE: Installed incorrectly

CORRECTION: Move striker plate a quarter of an inch to allow for proper operation
.20HRS

Labor

Job #	Description	Total
2	ENTRY DOOR ADJUST	38.00
Subtotal for Job #2:		38.00

Job #3 - Warranty

COMPLAINT: Spare tire holder loose

Customer #: 1000
MYERS "RV" CENTER,
INC.,



CAUSE: Unknown
Brown u bolt

CORRECTION: Need to order
Removed spare tire
Removed tire rack
Installed new tire rack
Reinstalled spare tire
Work completed

Labor

Job #	Description	Total
3	SPARE TIRE HOLDER	57.00

Parts

Part #	Description	Qty	Price	Total
F100468125	BRACKET, SPARE TIRE BUMPER MOUNT STANDARD 4"	1.00	40.61	40.61

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	19.67	19.67

Subtotal for Job #3: 117.28

Job #4 - Warranty

COMPLAINT: Water leak at rear of unit in underbelly

CAUSE: Incorrect installation

CORRECTION: During inspection water was leaking on ground when conducting flood test. Checked connections at shower , sink, and faucets. Removed access cover under all fixtures and performed leak test to ensure no pressure side leak present . Noted toilet level dropping . Inspected toilet seal but no leak noted.

Remove and install underbelly from rear bumper to Axle had to remove propane quick connect and metal clamps. Removed foam and reseal underbelly 3.4hrs

1st attempt repair using liquid beutle . Had to pull unit out of bay to dump water out to allow adhesive to cure. Flood tested for 15 minutes and unit still leaked 1.8hrs

2nd attempt repair using abs glue. Pulled unit out and dumped and allowed tank to dry. Removed tank flush and cleaned both surfaces. Applied abs glue and secured tank flush to base . Let cure and flood tested to ensure repair. Unit passed leak test. 3.2

8.00HRS

Labor

Job #	Description	Total
4	WATER SYSTEM PUMP DIAGNOSE	1,254.00

Parts

Part #	Description	Qty	Price	Total
06-7828	BUTYL RUBBER SEALANT - 10.1OZ TUBE (GRAY)	1.00	6.33	6.33

Subtotal for Job #4: 1,260.33

Job #5 - Warranty

COMPLAINT: Water pump turns on no pressure

CAUSE: Incorrect installation

CORRECTION: Winterize valave had loose clamps. Installed new clamps and tested. System functioning as designed
.50HRS

W/O: 72188
Promised Date: 06 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Labor		
Job #	Description	Total
5	WATER PUMP	57.00
Subtotal for Job #5:		57.00

Job #6 - Warranty

COMPLAINT: Black tank flush vacuum breaker leaking

CAUSE: Loose connection

CORRECTION: Tightened connections and re tested
 .50HRS

Labor		
Job #	Description	Total
6	BLACK TANK FLUSH	95.00
Subtotal for Job #6:		95.00

Job #7 - Warranty

COMPLAINT: Poor water pressure went on city hook up

CAUSE: Debris in fresh water system.

CORRECTION: Pulled all airator and removed debris. Flushed system until no debris noted.
 .20HRS

Labor		
Job #	Description	Total
7	CITY WATER PRESSURE	57.00

Parts				
Part #	Description	Qty	Price	Total
38-8522	TEFLON THREAD SEAL	1.00	0.40	0.40
Subtotal for Job #7:				57.40

Job #8 - Warranty

COMPLAINT: Door side rear stabilizer jack bent

CAUSE: Unknown
 Broken passenger side rear jack

CORRECTION: Not on DAF . Need to order
 Removed old jack
 One self drilling screw broke had to be removed to reinstalled new jack
 Installed new jack work completed

Labor		
Job #	Description	Total
8	STABILIZER	95.00

Parts				
Part #	Description	Qty	Price	Total
F100437865	JACK, 24" SCISSOR 2500#	1.00	26.47	26.47
Subtotal for Job #8:				121.47

Job #9 - Warranty

COMPLAINT: SPARE TIRE CARRIER U-BOLT IS BROKEN

CAUSE: OVERTIGHTENED

CORRECTION: REFERENCE JOB 3





Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: FRONT SHADE LOWER BRACKET IS BROKEN

CAUSE: Shade broken

CORRECTION: Removed 4 corner screws looked at the whole inside and out no labels found

Measurements 58 1/2 x 24 3/4 outside

New shade arrived had to completely assemble the shape

Installed new shade tested its operation works correctly job completed

Labor

Job #	Description	Total
10	SHADE BRACKETS	38.00

Parts

Part #	Description	Qty	Price	Total
F100551555	WINDOW, SCREEN/SHADE COMBO 50" RADIUS - BLACK	1.00	407.07	407.07

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	143.32	143.32

Subtotal for Job #10: 588.39

Job #11 - Warranty

COMPLAINT: L/S COMPARTMENT PANEL IS UNATTACHED

CAUSE: NOT SECURED PROPERLY

CORRECTION: REMOVE PANEL AND REMOVE STAPLES. REINSTALL AND RESTAPLE PANEL PROPERLY

.50HRS

Labor

Job #	Description	Total
11	PANEL	95.00

Subtotal for Job #11: 95.00

Job #12 - Warranty

COMPLAINT: Cabinet doors above stove not lined up evenly

CAUSE: Cabinet doors not even

CORRECTION: Hinges need to be adjusted

.10

Labor

Job #	Description	Total
12	CABINET DOOR ADJUST	19.00

Subtotal for Job #12: 19.00

Job #13 - Warranty

COMPLAINT: Counter top to the left of stove have deep gouges

CAUSE: Counter top damaged left side of cook top

CORRECTION: Removed all 3 drawers

Removed cook top cover and grate

Disconnected the gas line and power to the cook top

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



W/O: 72188
Promised Date: 06 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Removed trim piece screws and side screws took cook top out
Cut the silicone from the edges
Found the counter top was stapled in place from the bottom
Pried counter top loose from the staples
Unscrewed a side support
Cut several staples to get counter top loose
Cut and flatten out all staples
Removed side support from the damaged top
Attached side support to the new top
Used liquid nails along all edges
Placed new top in place
Stapled the top in the areas where the staple gun would fit
Used screws in two places the staple gun didnt fit
Put cook top in place attached the power and gas line
Leak tested the propane no leaks detected
Screwed cook top in placed
Installed the top and grate
Installed the trim on the back
Installed the drawers
Silicone sealed the edges
Work completed

Labor				
Job #	Description			Total
13	COUNTERTOP R&R			380.00

Parts				
Part #	Description	Qty	Price	Total
F100591615	COUNTERTOP, KITCHEN - ISLA OPAL (12-004200B)	1.00	74.84	74.84

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	54.39	54.39

Subtotal for Job #13: 509.23

Job #PDI1 - Internal

Transferred to RV*72188-1 on 21 NOV 25
Estimate amount was 0.00
PRE-PDI NEW TT - 3.0

Labor				
Job #	Description			Total
PDI1	PDI TRAVEL TRAILER			N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Parts Total: 555.72
Labour Total: 2,185.00
Sublet Total: 0.00
Extras Total: 217.38
WORK ORDER TOTAL: 2,958.10



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 05 Mar 2026

W/O: 72188
Promised Date: 06 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Customer Work
Order

