

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2449382  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TRPU19TB035153  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 080 / 080  
 ITEM # RPT185-80  
 DEALER RO # 72188  
 CLAIM START DATE 09/26/2025  
 CLAIM END DATE 03/05/2026

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 20-66-02-17-000672      Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-09-26 10:44:09 :: Entry door will not close / Installed incorrectly / Move striker plate a quarter of an inch to allow for proper operation  
**Model#**      **Dlr Sub Hrs**      0.20      **Sub Labor Amt** \$38.00  
**Serial#**      **Appr Hrs**      0.20      **Appr Labor Amt** \$38.00  
**Notes**

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 60-138-24-00-001535      Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-09-26 10:46:36 :: Water leak at rear of unit in underbelly Incorrect installation Had to gain access to black tank flush. Removed rear portion of underbelly from bumper to rear of axle. Removed sewer, spout, Support, propane, lines, and propane quick disconnect. Removed tank flush from tank cleaned both surfaces attempted to use similar product as manufacturer liquid beautle Decor brand. Product did not hold flood test. Removed tank flush, clean surface and used ABS glue secured tank flesh and flooded system. No leaks noted.  
**Model#**      **Dlr Sub Hrs**      8.00      **Sub Labor Amt** \$1,520.00  
**Serial#**      **Appr Hrs**      0.00      **Appr Labor Amt** \$0.00  
**Notes**  
 hello, can you explain more in depth on why the repair took 8 hours  
 We will hold onto this claim for 10 days awaiting a response. Thank you and have a wonderful day.  
  
 This claim has now been open for 10 days or more with no response. Due to the age of the claim, this claim has been denied, once all requested information is collected please resubmit the claim for review, Thank you!

### Labor

Line# 3      **Operation Code**      **Operational Description**  
 60-136-12-00-002120      Water Pump - Plumbing/Fresh Water Supply/Resecure or Tighten/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-09-26 11:07:21 :: Water pump turns on no pressure Incorrect installation Winterize valave had loose clamps. Installed new clamps and tested. System functioning as designed  
**Model#**      **Dlr Sub Hrs**      0.50      **Sub Labor Amt** \$95.00  
**Serial#**      **Appr Hrs**      0.30      **Appr Labor Amt** \$57.00

**Notes**

excessive time requested. Time reduced based on photos, description and flat rate.  
authorized to install new clamps

**Part**

<b>Line# 1</b>	<b>Item #</b>		<b>Description</b>			
	USERPART		Clamps			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00

**Notes**

**Labor**

<b>Line# 4</b>	<b>Operation Code</b>		<b>Operational Description</b>	
	60-138-24-00-001526		Termination Valve Cable - Plumbing/Drainage System/Repair/No Tread Code	
	<b>Complaint, Cause, Correction</b>			
	Original Note : ryliefayth@gmail.com, 2025-09-26 11:16:17 :: Black tank flush vacuum breaker leaking Loose connection Tightened connections and re tested			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b> \$95.00
	<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b> \$95.00

**Notes**

**Labor**

<b>Line# 5</b>	<b>Operation Code</b>		<b>Operational Description</b>	
	60-136-24-00-001497		Fresh Water Tank - Plumbing/Fresh Water Supply/Repair/No Tread Code	
	<b>Complaint, Cause, Correction</b>			
	Original Note : ryliefayth@gmail.com, 2025-09-26 11:22:19 :: Poor water pressure went on city hook up Debris in fresh water system. Pulled all airaitor and removed debris. Flushed system until no debris noted.			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$57.00
	<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$57.00

**Notes**

**Part**

<b>Line# 2</b>	<b>Item #</b>		<b>Description</b>			
	USERPART		38-8522 Teflon Thread Seal			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	1.00	Sub Dlr Price	\$0.40	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.40	Appr Freight	\$0.00

**Notes**

**Labor**

<b>Line# 6</b>	<b>Operation Code</b>		<b>Operational Description</b>	
	10-9-01-00-000162		Scissor Jack, each - Frame & Chassis/Levelers, Underbelly/Replace/No Tread Code	
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 21:33:36 :: Complaint: Door side rear stabilizer jack is bent Cause: Defective jack Correction: Remove and replace jack			
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b> \$95.00
	<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b> \$95.00

**Notes**

**Part**

<b>Line# 1</b>	<b>Item #</b>		<b>Description</b>			
	F100437865		JACK, 24" SCISSOR - 2500# *JS-SCJ-2500# 24"*			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	1.00	Sub Dlr Price	\$26.47	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$26.47	Appr Freight	\$0.00

Notes

Labor

Line# 7 Operation Code 10-3-01-00-000078 Operational Description Bumper Mount Spare Tire Carrier - Frame & Chassis/Wheels, Tires, Hubcaps/ Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 21:35:29 :: Complaint: Spare tire carrier u bolt is broken Cause: Overtightened Correction: Replace u bolt

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$57.00
Serial# Appr Hrs 0.30 Appr Labor Amt \$57.00

Notes

Part

Line# 1 Item # F100468125 Description BRACKET, SPARE TIRE BUMPER MOUNT STANDARD 4" \*\*TC-TC3-BULK\*\*
Model # Serial # Part tag 0000404893
Sub Qty 1.00 Sub Dlr Price \$40.61 Sub Freight \$19.67
Appr Qty 1.00 Appr Dlr Price \$40.61 Appr Freight \$19.67

Notes

Labor

Line# 8 Operation Code 30-99-24-00-001018 Operational Description Day Night Shade or Roller Shade - Interior/Soft Goods/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 21:37:18 :: Complaint: Front shade lower bracket is broken Cause: Defective brackets Correction: Replace brackets Additional Note : stephanie@dealer-advisors.com, 2025-12-18 21:38:07 :: \*\*closest labor operation for this repair\*\*

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$38.00
Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

Part

Line# 1 Item # F100551555 Description WINDOW, SCREEN/SHADE COMBO, 50" RADIUS, BLACK
Model # Serial # Part tag
Sub Qty 1.00 Sub Dlr Price \$407.07 Sub Freight \$143.32
Appr Qty 1.00 Appr Dlr Price \$407.07 Appr Freight \$143.32

Notes

Labor

Line# 9 Operation Code 30-102-12-00-002691 Operational Description Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 21:38:54 :: Complaint: Left side compartment panel is unattached Cause: Not secured properly Correction: Remove panel and remove staples, reinstall and restaple panel properly

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00
Serial# Appr Hrs 0.50 Appr Labor Amt \$95.00

Notes

authorized to repair as stated

Part

Line# 1 Item # USERPART Description Staples
Model # Serial # Part tag
Sub Qty 1.00 Sub Dlr Price \$4.75 Sub Freight \$0.00

Appr Qty 1.00 Appr Dlr Price \$4.75 Appr Freight \$0.00  
Notes

---

**Submitted**

Labor Amt \$2,090.00  
Parts & Freight \$645.14  
Total \$2,735.14

**Approved**

Labor Amt \$532.00  
Parts & Freight \$645.14  
Total \$1,177.14

---

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

All repairs described have been inspected and are satisfactory.