

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2551396
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRPU19TB035153
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080
 ITEM # RPT185-80
 DEALER RO # 72188
 CLAIM START DATE 01/14/2026
 CLAIM END DATE 03/05/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 10-9-15-00-000168	Operational Description Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/ No Tread Code
---------	-------------------------------------	--

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-14 16:39:46 :: This job was denied once with notations on claim 2449382 to provide a better story to support the labor. Complaint: Water leak at rear of unit in underbelly. Cause: During inspection water was leaking on ground when conducting the flood test. Checked connections at the shower, sink and faucets. Removed access cover under all fixtures and performed leak test to ensure no pressure side leak present. Noted toilet level dropping. Inspected toilet seal, but no leak noted. Correction: Remove and install underbelly from rear bumper to axle. Had to remove propane quick connect and metal clamps. Removed foam seal and reseal underbelly, 3.4 hours. First attempt at repair using liquid butyl, had to pull unit out of bay to dump water out to allow adhesive to cure. Flood tested for 15 minutes and unit still leaks - 1.8 hours. Second repair attempt using ABS glue, pulled unit out and dumped and allowed tank to dry. Removed tank flush and cleaned both surfaces. Applied ABS glue and secure tank flush to base. Let cure and flood tested to ensure repair. Unit passed leak test - 3.2 hours.

Model#	Dlr Sub Hrs	8.40	Sub Labor Amt	\$1,596.00
Serial#	Appr Hrs	6.60	Appr Labor Amt	\$1,254.00

Notes

We can offer 6.6 for the first repair and last. The second repair that didn't work we would not be able to offer anytime as the fix didn't correct it.

Part

Line# 1	Item #	Description
	USERPART	06-7828 Butyl Rubber Sealant 10.1OZ Tube
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$6.33
	Appr Qty 1.00	Appr Dlr Price \$6.33
		Part tag
		Sub Freight \$0.00
		Appr Freight \$0.00

Notes

Labor

Line# 3	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-09 17:39:06 :: Complaint: Cabinet doors above stove are not lined up properly Cause: Cabinet doors are not even Correction: Adjust hinges

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes

Labor

Line# 4

Operation Code

30-100-01-00-001054

Operational Description

Kitchen/Galley Countertop - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-09 17:41:04 :: Complaint: Countertop to the left of the stove has deep gouges Cause: Unknown Correction: Replace countertop, will need to pull stove, remove countertop, and silicone. Install new countertop, res silicone and reinstall stove. Perform LP gas pressure test.

Model#**Dlr Sub Hrs**

2.00

Sub Labor Amt \$380.00**Serial#****Appr Hrs**

2.00

Appr Labor Amt \$380.00**Notes**

In order to review this repair line, a photograph is required. Please upload photos to this repair line.

Pictures added
authorized to replace

Part

Line# 1

Item #

F100591615

Description

COUNTERTOP, KITCHEN (12-004200b)- ISLA OPAL **695083**

Model #**Serial #****Part tag****Sub Qty** 1.00**Sub Dlr Price** \$74.84**Sub Freight** \$54.39**Appr Qty** 1.00**Appr Dlr Price** \$74.84**Appr Freight** \$54.39**Notes****Submitted**

Labor Amt \$1,995.00

Parts & Freight \$135.56

Total \$2,130.56

Approved

Labor Amt \$1,653.00

Parts & Freight \$135.56

Total \$1,788.56

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.