



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72801
 Promised Date:
 02 JAN 26



WO #: 72801 (Appointment Date: 02 JAN 2026 - Time: 01:15pm)
 Customer Name: 59726 - GUTHRIE, JULIA CAROL
 Completed Date: 17 FEB 26
 Invoice#: Author: BRIAN
 Stock Desc: 9473 2025 R-POD RP-206
 Serial#: 4X4TRPW2XSB033870
 Chassis#: 4X4TRPW2XSB033870 Date In: 02 JAN 26
 Miles/Hrs: Time In:
 Tag#: 6975
 Purchased Date: 19 APR 25
 Warranty Date: 19 APR 25

Job #0 - Warranty

CLAIMS: 2547759 / 2547463

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES TOP PANTRY SHELF COMING APART

CAUSE: No structural support at front causing shelf movement and detachment of front cross beam.

CORRECTION: Removed hardware. Repaired wood. Custom fabricated support brackets for each side of shelf. Screwed brackets into structural support in wall. Reattached front cross beam with fasteners to new support bracket. Reinstalled netting. Completed
 Requesting 1.0 hr

Labor

Job #	Description	Total
1	PANTRY SHELF	190.00

Subtotal for Job #1: 190.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES TRIM AT SIDE OF BED LOOSE

CAUSE: Detached

CORRECTION: Removed fasteners. Repaired trim. Reinstalled and covered staple holes with putty. Completed.
 Asking 3hr

Labor

Job #	Description	Total
2	TRIM	19.00

Subtotal for Job #2: 19.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES CITY WATER INLET LOOSE

CAUSE: Holes in wall stripped

Customer #: 59726
 GUTHRIE, JULIA CAROL



CORRECTION: Removed city water receptacle. Removed silicone. Repaired holes with sealant. Drilled new holes and reinstalled city water receptacle. Resealed with clear silicone. Requesting .5 hr

Labor		
Job #	Description	Total
3	CITY WATER INLE	57.00

Parts				
Part #	Description	Qty	Price	Total
40170	SILICONE TUBE-CLEAR	1.00	10.53	10.53
Subtotal for Job #3:				67.53

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES BATHROOM SINK LOOSE (NOT SEALED)

CAUSE: Brackets loose. Not secured. No sealant around sink

CORRECTION: Tightened brackets. Secured to counter with fasteners to prevent future movement. Sealed sink with clear silicone.
Requesting 1.0 hr

Labor		
Job #	Description	Total
4	BATHROOM SINK	95.00
Subtotal for Job #4:		95.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES FLOOR IS GETTING DAMAGED BY SLIDE

CAUSE: Couch nylon rub tab has damaged floor.
Slide room damaged Lino

CORRECTION: Remove couch fasteners and shim couch to allow for floor clearance when slide is closed.
Sublet floor repair
Slide was adjusted on prior work order
Two full planks were cut out 8 inches wide 8 foot 10 inches long
New Lino was laid out and the same planks were located
New piece cut out then matched with the old piece the was removed
New piece was trimmed to fit
The floor was cleaned and all edges were trimmed of any fraying
Dicor glue was used and brushed on to he floor and under the old Lino about 4 inches
The new piece was worked into place trimmed as needed along the edges
Hand roller was used over the whole area to ensure all the glue adhered and along the seam edges
Once it was fit completely in place boards and weights were placed on the seams and allowed to sit over the weekend
Weights and boards were removed the seam was checked and remained in place
Seam sealer was then applied to all cut edges excess was cleaned away
Seam sealer was allowed to completely dry and rechecked all cut edges are sealed
Work completed

Labor		
Job #	Description	Total
5	FLOOR	380.00

Parts				
Part #	Description	Qty	Price	Total
F100533102	LINO, EUROPEAN OAK SANDBAR, CC335 - 2025	6.00	12.73	76.38

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	143.32	143.32

W/O: 72801
Promised Date: 30 JAN 26



Customer #: 59726
GUTHRIE, JULIA CAROL





Subtotal for Job #5: 599.70

Job #5A - Warranty

COMPLAINT: CUSTOMER STATES REPAIR SOFA

CAUSE: Shim. Adjust and test sofa for floor clearance

CORRECTION: Completed

Labor

Job #	Description	Total
5A	SOFA	380.00

Subtotal for Job #5A: 380.00

Job #6 - Internal

COMPLAINT: CUSTOMER STATES TPMS WILL NOT SET UP

CAUSE: Not programmed correctly

CORRECTION: Performed factory reset on tpms. Performed high and low pressure progamming. Learned in all 4 tires. Tested. Completed .5 hr requesting

Labor

Job #	Description	Total
6	TPMS	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES KITCHEN FAUCET LOOSE

CAUSE: Improper installation of set nut.

CORRECTION: Reinstalled sink properly. Tightened set nut screws after reinstallation to prevent future loosening. Tested. Completed Requesting.5 hr

Labor

Job #	Description	Total
7	KITCHEN FAUCET	57.00

Subtotal for Job #7: 57.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES RIVETS FOR WHEEL WELLS LOOSE

CAUSE: Hole stripped.

CORRECTION: Installed new black fastener to enlarged hole and sealed. Completed Requesting .3 hr

Labor

Job #	Description	Total
8	WHEEL WELLS	57.00

Subtotal for Job #8: 57.00

Job #9 - Warranty

COMPLAINT: CUSTOMER STATES MICROWAVE DOOR HARD TO OPEN

CAUSE: Microwave not centered in hole causing trim ring to bind on door.



CORRECTION: Removed microwave. Installed shims inside trim ring area to allow door to sit center without rubbing. Resecured trim ring. Completed Requesting.5 hr

Labor

Job #	Description	Total
9	MICROWAVE	57.00

Subtotal for Job #9: 57.00

Parts Total: 86.91
Labour Total: 1,292.00
Sublet Total: 0.00
Extras Total: 143.32
WORK ORDER TOTAL: 1,522.23

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 05 Mar 2026

W/O: 72801
Promised Date: 30 JAN 26



Customer #: 59726
GUTHRIE, JULIA CAROL

