

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2547759
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	4X4TRPW2XSB033870
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	080 / 080
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	RPT206-80
JULIA GUTHRIE		<b>DEALER RO #</b>	72801
390 BARRED ROCK CT		<b>CLAIM START DATE</b>	01/12/2026
Las Cruces, NM 88007		<b>CLAIM END DATE</b>	02/17/2026
USA			
<b>Retail Date of Purchase</b>	04/19/2025	<b>WARRANTY EXPIRATION DATE</b>	04/19/2026

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>
	30-91-24-00-000923	Furniture - Sofa or Chairs - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code

#### Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-12 12:28:51 :: Complaint: Floor is being damaged by slide Cause: Couch nylon rub tab has damaged the floor Correction: Remove couch fasteners and shim couch to allow for floor clearance when slide is closed. Repair to flooring is on 2547463.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	2.00	<b>Sub Labor Amt</b>	\$380.00
<b>Serial#</b>	<b>Appr Hrs</b>	2.00	<b>Appr Labor Amt</b>	\$380.00

#### Notes

hello, can you show where the slide is damaged?  
 The slide is not damaged, the couch nylon rub tab has damaged the floor. The flooring repair is on a different PA (2547463). We were asked to separate the flooring and the couch repair. This line is for the couch repair.  
 authorized to repair as stated

<b>Submitted</b>	Labor Amt	\$380.00	<b>Approved</b>	Labor Amt	\$380.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$380.00		Total	\$380.00

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.