

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2610377
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TUMA23TB035532
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080B
 ITEM # UMT25RL-80
 DEALER RO # 73034
 CLAIM START DATE 03/16/2026
 CLAIM END DATE 03/17/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-101-24-00-001074	Operational Description Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No Tread Code
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-03-16 12:21:44 :: Complaint: Pocket door is not functioning
 Cause: There is a brace on the inside of the wall for the pocket door. The staples did not hold and the wood popped out enough to make contact with the door when it is fully closed. Correction: Remove the upper header board, unclipped the door and removed the door from the track. Unsecured the piece of wood. Can hold piece of wood up against the wood panel and staple the wood panel being the toilet to resecure the board inside the wall
 Fill all holes with putty and stain to match. Rehang the door and reinstall the header board.

Model#	Dlr Sub Hrs	0.85	Sub Labor Amt	\$161.50
Serial#	Appr Hrs	0.85	Appr Labor Amt	\$161.50

Notes

changed to more suitable code
 Authorized to repair as stated.

Part

Line# 1	Item # USERPART	Description Stain and putty			
	Model #	Serial #	Part tag		
	Sub Qty	Sub Dlr Price	Sub Freight	\$8.08	\$0.00
	Appr Qty	Appr Dlr Price	Appr Freight	\$8.08	\$0.00

Notes

Submitted	Labor Amt	\$161.50		Approved	Labor Amt	\$161.50
	Parts & Freight	\$8.08			Parts & Freight	\$8.08
	Total	\$169.58			Total	\$169.58

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.