

ATTN:
 DATE: 10-16-25



An AIRXCEL Brand

RVP TECH: ONLINE
 TRACKING #: BLANKET

COOLING PERFORMANCE WORKSHEET

❖ THIS IS NOT A CLAIM FORM ❖

THIS FORM WILL NEED TO BE COMPLETED ENTIRELY. OR THE REQUEST WILL BE DENIED
This form cannot be submitted until all required sections have been completed and signed. Once you complete the signature field this form will automatically save a copy to your computer, then please click the SUBMIT button.

COOLING PERFORMANCE CHECKOUT PROCEDURES:

SECTION 1: (Required)

FACILITY NAME: TriAm RV Center		
ADDRESS: 1202 Idell Rd		
CITY: Bulls Gap	ST: TN	ZIP: 37711
PHONE: 423-235-1167		
EMAIL: tnwarranty@triamrv.com		

SECTION 2: (Required)

AC/HP MODEL:	38203-069
AC/HP SERIAL #:	250021023
DATE OF PURCHASE:	7-21-25
WHAT TYPE OF APPLICATION IS THIS UNIT INSTALLED ON?	2025 KZ Sportsmen
PO NUMBER:	26141

SECTION 3:

Does the compressor attempt to start?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
Voltage to Unit?	123	VOLTS AC
Is the compressor tripping?	<input type="checkbox"/> OVERLOAD	<input type="checkbox"/> BREAKER
Amp Draw (black wire at compressor)?	9.2	AMPS
PTCR/Start Kit Good?	<input type="checkbox"/> YES	<input type="checkbox"/> NO
Ceiling Assembly Type:	<input type="checkbox"/> DUCTED	
	<input checked="" type="checkbox"/> NON-DUCTED	
	<input type="checkbox"/> NONE	

SECTION 4:

To complete the following, you **MUST** START and RUN the unit in the HIGH COOL position for 15-20 minutes prior to taking ANY measurements.
DO NOT USE A LASER THERMOMETER

Outdoor Temperature:	73.2	°F
Temp at Return Air Grill:	72.8	°F
Temp at Supply Register:	59.3	°F

SECTION 5: (OEM INFO)

VIN:	4E2TK181S5046256
PRE-AUTHORIZATION #:	

SECTION 6: (DEALER INFO)

DEALER NUMBER:	12582
ADVISOR NAME:	Stephanie

SECTION 7:

NOTE: By signing and dating this form, you verify and guarantee the information as recorded above is truthful and accurate.

DATE

IF THE AIR CONDITIONER IS RETURNED TO US, AND OUR DIAGNOSTIC CHECKOUT PROVES THE AIR CONDITIONER IS OPERATING PROPERLY, YOUR FIRM WILL BE CHARGED FOR THE AIR CONDITIONER AND ASSOCIATED FREIGHT COSTS.

❖ If you don't receive a response within 24 hours, please contact us! ❖



AUTHORIZED SIGNATURE OF RESPONSIBLE PARTY

If this form cannot be completed using Adobe Acrobat Reader, please download a copy, complete and email to RVPCPW@airxcel.com