

Print Close

Claim - 2226990 (Paid)

Print Label View UPS Label

(/campaign/?vin=4X4TRLX22SD462402&fromState=Claims&fromItem=2226990) (/campaign/?vin=4X4TRLX22SD462402&fromState=Claims&fromItem=2226990)VIN

4X4TRLX22SD462402

Dealer RO

25128

Dealer Contact

Olsen, Ashlee (ashlee@dealer-advisors.com) ▼

Claim Start

03/12/2025

Claim End

03/26/2025

Chassis#

Owner

JAMES YEHL

Brand

ROCKWOOD

PDF viewer overlay showing page 1 of 2 with navigation icons.

Model

RLT2205S

Year

2025

Warranty Start

03/27/2025

Warranty End

03/27/2026

Rate

\$165.00

Original Claim #

Submitted Total

\$479.57

Approved Total

\$463.07


Paid Total

\$463.07

Payment Date

04/07/2025

Check Number



2949969

Dealer Address

1202 IDELL ROAD (I-81 EXIT 23) BULLS GAP, TN 37711 USA

Related Claims

▼ **Labor 1** (Approved) Original Note : ashlee@dealer-advisors.com, 2025-03-12 08:58:19 :: Complaint: Chip in stile above the recliner Cause: Noted on DAF. Damaged at the ti...

Notes & Feedback

Complaint, Cause, Correction

ⓘ Requested hours is greater than allowed hours. Pre-authorization required.

Flat Rate Code

Flat Rate

Sublet PreAuth

Hours Labor Amt

Model Serial

Photo Req. US CAN

Return Req. US CAN

30-100-01-00-001050

Notes

0.



Requested 1.

\$



Description

Interior/Cabinetry/Replace/No Tread Code - Cabinet Stiles

Approved: 1.

\$

Part 1 (Approved)

Notes & Feedback



#	Part#	Qty	Submitted Cost	Dealer Cost	Markup %	Freight	Crate	Submitted Total	Approved Total	Part Tag	Receipt Req.
1	F10034710	1	\$6.93	\$6.93	30.00	\$129.21	\$13.00	\$151.22	\$151.22		

Model

Serial

Description

STILE - PFL: RADIUS EDGE - SEDONAWOOD - 2" X 8' - V# 47082906

▼ **Labor 2** (Approved)

Original Note : ashlee@dealer-advisors.com, 2025-03-12

Notes & Feedback

Complaint, Cause, Correction

08:59:58 :: Complaint: Entry door lock will not allow you to lock the door. Lock will not turn...

ⓘ When an authorization is not required on the flat rate code, the system will auto-authorize the repair. Please note that the labor line is still subject to review at the processing level. Forest River will need to verify that the correct repair was made and is warrantable, the correct code was used, the requirements have been met, and the description provided us information to substantiate the repair. It may still be adjusted or denied based on the review.

Flat Rate Code

Flat Rate

Sublet PreAuth

Hours Labor Amt

Model Serial

Photo Req. US CAN

Return Req. US CAN

20-66-01-17-000668

Notes

0.



Requested 0.

\$4



Description



Exterior/Entry Doors/Replace/Latch - Entry Door Lock

Approved: 0.

\$4

Part 1 (Approved)

Notes & Feedback 

#	Part#	Qty	Submitted Cost	Dealer Cost	Markup %	Freight	Crate	Submitted Total	Approved Total	Part Tag	Receipt Req.
1	F10029763	1	\$42.93	\$42.93	30.00	\$5.00	\$0.00	\$60.81	\$60.81		 
Model		Serial		Description							
				ENTRANCE DOOR PART - 3F-3: GLOBAL LATCH LOCK W/ PLUGS, TRAVEL TRAILER, KEYED ALIKE - BLACK - V# 2021126742 LOCK CYLINDER NOT INCLUDED, REPLACED V# 257983							



Part 2 (Approved)

Notes & Feedback 

#	Part#	Qty	Submitted Cost	Dealer Cost	Markup %	Freight	Crate	Submitted Total	Approved Total	Part Tag	Receipt Req.
2	F10021189	1	\$1.07	\$1.07	30.00	\$0.00	\$0.00	\$1.39	\$1.39		 
Model		Serial		Description							
				LOCK PART - 7H-3: DEADBOLT LOCK CYLINDER FOR KEYED ALIKE, NON-MASTER - V# KC-SNM-NK-361-370 SPECIFY KEY NUMBER NEEDED 361-370, KEY PURCHASED SEPARATELY							

Part 3 (Approved)

Notes & Feedback 

#	Part#	Qty	Submitted Cost	Dealer Cost	Markup %	Freight	Crate	Submitted Total	Approved Total	Part Tag	Receipt Req.
3	F10022087	1	\$1.65	\$1.65	30.00	\$0.00	\$0.00	\$2.15	\$2.15		 
Model		Serial		Description							
				LOCK PART - 7H-3: DOOR LOCK CYLINDER FOR KEYED ALIKE, MASTER - V# KC-SM-NK-361-370 SPECIFY KEY NUMBER NEEDED 361-370, KEY PURCHASED SEPARATELY							

▼ Labor 3

(Approved) Original Note : ashlee@dealer-advisors.com, 2025-03-12

Notes & Feedback

Complaint, Cause, Correction

09:00:46 :: Complaint: Grab handle at the entry door to the left has several scratches and mar...

ⓘ Requested hours is greater than allowed hours. Pre-authorization required.

Flat Rate Code

Flat Rate

Sublet

PreAuth

Hours

Labor Amt

Model

Serial

Photo Req. US CAN

Return Req. US CAN

20-66-01-16-000689

Notes

0.



Requested 0.

\$:



Description

Exterior/Entry Doors/Replace/Structure - Assist Door Handle - Folding

Approved: 0.

\$: