



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25160



WO #: 25160 (Appointment Date: 24 MAR 2025 - Time: 09:00am)

Customer: 74694 - RENNER, RANDY  
 Address: 285 STONE DAM RD  
 CHUCKEY, TN  
 37641

Home Phone: (423) 620-3782

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10913

Stock Desc: 2024 FW FOREST RIVER

SANDPIPER 4003MB

Model: 4003MB

Serial #: 4X4FSAS28RJ046573

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 02 NOV 24

Date In: 21 MAR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 02 NOV 24

**Job #1 - External**

INSTALL ORDERED SLIDE TOPPERS

**Parts**

Part #	Description	Qty	Price	Total
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	12.59	12.59
79233	BUTYL TAPE 1/8X3/4	1.00	11.69	11.69
00-0485	SLIDETOPPER BLACK LIPPERT 80-85 3/4	2.00	402.29	804.58
00-0496	V000165061 LCI SLIDE OUT TOPPER 156"	1.00	508.49	508.49

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

**Subtotal for Job #1: 1,337.35**

**Job #2 - Warranty**

COMPLAINT: TRIM LOOSE AT THE ENTRY DOOR INTERIOR TRIM

CAUSE: TRIM CAME LOOSE AND FALLING DOWN

CORRECTION: RESECURE TRIM AT ENTRY DOOR  
 LABOR .2

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: TRIM LOOSE AT THE TV IN THE LIVING AREA

CAUSE: TRIM NOT SECURED IN CORRECT PLACE

CORRECTION: RESECURE TRIM IN PLACE  
 LABOR .2

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: PANTRY WILL NOT GO IN THE LOCK POSITION  
 DOOR SLINGS OPEN

Customer #: 74694  
 RENNER, RANDY



CAUSE: BARRAL LATCH IS NOT LINING UP WITH THE CATCH. THIS ISSUE IS NOT ALLOWING THE PANTRY DOOR TO STAY CLOSED AND LATCHED.

CORRECTION: REMOVE CATCH, LOCATE CATCH TO LINE UP WITH THE LATCH  
LABOR .2

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: GRAY TANK LEAKING CUST STATED WHEN IT GOT FULL IT WILL LEAK  
CUST SPOKE TO RUSS ABOUT THE ISSUE

CAUSE: WATER FROM SHOWER IS LEAKING OUT AROUND THE PAN AND WATER IS GETTING INTO OVER HANG COMPARTMENT AREA.

CORRECTION: SHOWER NEEDS TO BE RESEALED AND TESTED  
LABOR .30

**Subtotal for Job #5: 0.00**

Parts Total:	1,337.35
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	130.39

**WORK ORDER TOTAL: 1,467.74**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 26 Mar 2025

Customer Signature : \_\_\_\_\_

W/O: 25160



Customer #: 74694  
RENNER, RANDY

