



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25160



WO #: 25160 (Appointment Date: 24 MAR 2025 - Time: 09:00am)

Customer: 74694 - RENNER, RANDY
 Address: 285 STONE DAM RD
 CHUCKEY, TN
 37641

Home Phone: (423) 620-3782

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10913
 Stock Desc: 2024 FW FOREST RIVER
 SANDPIPER 4003MB
 Model: 4003MB
 Serial #: 4X4FSAS28RJ046573
 Chassis #:
 Mileage:
 Key #: 8500
 Req'n #:
 License #:
 Trim:

Purchase Date: 02 NOV 24
 Date In: 21 MAR 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date: 02 NOV 24

Job #1 - External

INSTALL ORDERED SLIDE TOPPERS

Labor

Job #	Description	Hours	Total
1	INSTALL SLIDE TOPPERS	4.00	N/C

Parts

Part #	Description	Qty	Price	Total
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	N/C	N/C
79233	BUTYL TAPE 1/8X3/4	1.00	N/C	N/C
00-0485	SLIDETOPPER BLACK LIPPERT 80-85 3/4	2.00	N/C	N/C
00-0496	V000165061 LCI SLIDE OUT TOPPER 156"	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: TRIM LOOSE AT THE ENTRY DOOR INTERIOR TRIM

CAUSE: TRIM CAME LOOSE AND FALLING DOWN

CORRECTION: RESECURE TRIM AT ENTRY DOOR

LABOR .2

Labor

Job #	Description	Hours	Total
2	RESECURED TRIM IN PLACE	0.20	33.00

Subtotal for Job #2: 33.00

Job #3 - Warranty

COMPLAINT: TRIM LOOSE AT THE TV IN THE LIVING AREA

CAUSE: TRIM NOT SECURED IN CORRECT PLACE

CORRECTION: RESECURE TRIM IN PLACE

LABOR .2

Customer #: 74694
 RENNER, RANDY



Labor			
Job #	Description	Hours	Total
3	RESECURED TRIM	0.20	33.00
Subtotal for Job #3:			33.00

Job #4 - Warranty

COMPLAINT: PANTRY WILL NOT GO IN THE LOCK POSITION
DOOR SLINGS OPEN

CAUSE: BARRAL LATCH IS NOT LINING UP WITH THE CATCH. THIS ISSUE IS NOT ALLOWING THE PANTRY DOOR TO STAY CLOSED AND LATCHED.

CORRECTION: REMOVE CATCH, LOCATE CATCH TO LINE UP WITH THE LATCH
LABOR .2

Labor			
Job #	Description	Hours	Total
4	ADJUSTED CATCH	0.20	33.00
Subtotal for Job #4:			33.00

Job #5 - Warranty

COMPLAINT: GRAY TANK LEAKING CUST STATED WHEN IT GOT FULL IT WILL LEAK
CUST SPOKE TO RUSS ABOUT THE ISSUE

CAUSE: WATER FROM SHOWER IS LEAKING OUT AROUND THE PAN AND WATER IS GETTING INTO OVER HANG COMPARTMENT AREA.

CORRECTION: SHOWER NEEDS TO BE RESEALED AND TESTED
LABOR .30

Labor			
Job #	Description	Hours	Total
5	RESEALED SHOWER AND TESTED FOR WATER	0.50	82.50

Parts				
Part #	Description	Qty	Price	Total
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	10.26	10.26
Subtotal for Job #5:				92.76



Customer #: 74694
RENNER, RANDY



Parts Total:	10.26
Labour Total:	181.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	191.76

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 28 Mar 2025

Customer Signature : _____

