

stated when it got full, it will leak. Customer spoke to Russ about the issue Cause: Water from shower is leaking out around the pan, and water is getting into overhang compartment area. Correction: Shower needs to be resealed and tested

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$82.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$82.50

Notes

Part

Line# 1	Item #		Description			
	USERPART		Proflex sealant CLR 100Z			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$10.26	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$10.26	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$181.50	Approved	Labor Amt	\$181.50
	Parts & Freight	\$10.26		Parts & Freight	\$10.26
	Total	\$191.76		Total	\$191.76

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.