

KZRV, LP APPOINTMENT DATE VEHICLE ARRIVED WSO DATE PRE
 Sportsmen - New Vision 3/31/2025 3/31/2025

REPAIR COMPLETION DATE CUSTOMER NOTIFIED VEHICLE PICK
 4/23/2025

RV SERIAL # MAKE MODEL
 4EZTL2326P707052 Lookup CONNECT C211MKSE
 DEALER ... CUSTOMER ...

DEALER # DEALER NAME CONTACT DENIA
 TRI030 Tri-Am RV Center of E. Tn, Inc JAMES & CHERYL QUICK
 LABOR RATE FEE RATE ADDRESS TELEPHONE
 175.00 15.00 114 MOUNTAIN RI
 ADDRESS TELEPHONE CITY STATE ZIP EQUIP
 1202 Idell Road JONESBOROUGH TN 37659 EQUIP
 CITY STATE ZIP EQUIP
 Bulls Gap TN 37711 EQUIP

JOB OPERATION 1 CAUSE OPER
 Customer said there is low flow coming from the furnace, furnace runs good Tech found blockage right at the furnace not allowing flow to the unit as designed to do 885
 INITIALS REMEDY SUPP
 Need to pull the underbelly, remove the plate that is blocking air flow in ducting, and reinstall underbelly. LABC
 PART

PART #	PART #	PART DESCRIPTION	PART DESCRIPTION	QTY	UNIT RETURN \$	TAG #	TO PAF
13-1610		Darco repair tape 4"		5	0.36	1.80	

Delete

SUB-1

JOB OPERATION 2 CAUSE OPER
 Dinette table is loose Screws pulled loose on both dinette table and polls. The screws that were installed at factory are not 557
 INITIALS REMEDY SUPP
 Remove 1/4" screws and replace with 1" screws to secure in place LABC
 PART

Delete

SUB-1

UPS Label