



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25200



WO #: 25200

Customer: 57896 - ADCOX, JAMES
Address: 300 CAMBY DR
KINGSPORT, TN
37664

Home Phone: 423-765-6863

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 10697
Stock Desc: 2023 A FOREST RIVER MIRADA
35OS
Model: 35OS
Serial #: 5ZTAMD001PM517566
Chassis #: 1F66F5DN8M0A15656
Mileage: 966
Key #: 8000
Req'n #:
License #:
Trim:

Purchase Date: 11 JUL 24
Date In: 31 MAR 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 11 JUL 24

Job #1 - Warranty

COMPLAINT: LIVING ROOM SLIDE IS NOT GOING IN AND OUT

CAUSE: SLIDE MOTOR WILL NOT MOVE BUT DOES HAVE POWER AND GROUND GOING TO IT.
WATER IS LEAKING FROM THE WIPER SEAL NOT BEING INSTALLED CORRECTLY FROM FACTORY.

CORRECTION: REMOVE FASCIA TO ACCESS MOTOR AND THE MECHANISM COVER TO ACCESS
MOTOR
REMOVE AND REPLACE THE SLIDE MOTOR
LABOR 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: FASCIA ON LIVING ROOM SLIDE HAD TO BE REMOVED IN ORDER TO ACCESS THE
SLIDE MOTOR. WHEN TECH REMOVED FASCIA WE FOUND WATER DAMAGE ON LEFT SIDE.

CAUSE: TOP WIPER SEAL ON SLIDE OUT ALLOWED WATER TO RUN DOWN THE SIDE DAMAGING
THE INTERIOR FASCIA, RIM BOARD AND THE STILE PIECES IN THIS AREA.

CORRECTION: SLIDE NEEDS TO BE PULLED IN ORDER TO REMOVE AND REPLACE ALL DAMAGED
WOOD IN THIS AREA. THIS SLIDE HOLDS A TABLE, CHAIRS AND DOUBLE SEATING THAT HAS TO
BE R&R. CLEAN SLIDE MATERIAL TOP TO BOTTOM TO REMOVE ALL THE MOLD.
LABOR 6.0

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 57896
ADCOX, JAMES




Customer Signature : _____

Date: 01 Apr 2025

W/O: 25200

Customer Work Order



Customer #: 57896
ADCOX, JAMES

