



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25200



WO #: 25200

Customer: 57896 - ADCOX, JAMES
 Address: 300 CAMBY DR
 KINGSFORT, TN
 37664

Home Phone: 423-765-6863

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10697

Stock Desc: 2023 A FOREST RIVER MIRADA
 350S

Model: 350S

Serial #: 5ZTAMD001PM517566

Chassis #: 1F66F5DN8M0A15656

Mileage:966

Key #: 8000

Req'n #:

License #:

Trim:

Purchase Date: 11 JUL 24

Date In: 31 MAR 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 01 JUL 25

Warr. Date: 11 JUL 24

Job #1 - Warranty

COMPLAINT: LIVING ROOM SLIDE IS NOT GOING IN AND OUT

CAUSE: SLIDE MOTOR WILL NOT MOVE BUT DOES HAVE POWER AND GROUND GOING TO IT.
 WATER IS LEAKING FROM THE WIPER SEAL NOT BEING INSTALLED CORRECTLY FROM FACTORY.

CORRECTION: REMOVE FASCIA TO ACCESS MOTOR AND THE MECHANISM COVER TO ACCESS
 MOTOR

REMOVE AND REPLACE THE SLIDE MOTOR

LABOR 1.0

Labor

Job #	Description	Hours	Total
1	MISC. LABOR CODE	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
C01259667	MOTOR 42 MM IN WALL SLIDE - MID TORQUE W/ BRAKE	1.00	196.10	196.10

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	18.43	18.43

Subtotal for Job #1: 379.53

Job #2 - Warranty

COMPLAINT: FASCIA ON LIVING ROOM SLIDE HAD TO BE REMOVED IN ORDER TO ACCESS THE
 SLIDE MOTOR. WHEN TECH REMOVED FASCIA WE FOUND WATER DAMAGE ON LEFT SIDE.

CAUSE: TOP WIPER SEAL ON SLIDE OUT ALLOWED WATER TO RUN DOWN THE SIDE DAMAGING
 THE INTERIOR FASCIA, RIM BOARD AND THE STILE PIECES IN THIS AREA.

CORRECTION: SLIDE NEEDS TO BE PULLED IN ORDER TO REMOVE AND REPLACE ALL DAMAGED
 WOOD IN THIS AREA. THIS SLIDE HOLDS A TABLE, CHAIRS AND DOUBLE SEATING THAT HAS TO
 BE R&R. CLEAN SLIDE MATERIAL TOP TO BOTTOM TO REMOVE ALL THE MOLD.

LABOR 6.0

Labor

Job #	Description	Hours	Total
2	REPLACED ALL DAMAGED FASCIA	7.00	1,155.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 57896
 ADCOX, JAMES



F100220643	TAPE, SEAM MATTE LUX VELVET WHITE, 6"-	24.00	1.31	31.44
F100201703	FASCIA, BLOCK CORNER RT WHITE VELVET	1.00	37.12	37.12
F100201701	FASCIA, BLOCK CORNER RT INSERT WHITE VELVET	1.00	6.01	6.01

Subtotal for Job #2: 1,229.57

Job #3 - Warranty

COMPLAINT: AS REQUESTED BY FOREST RIVER TO ADD A LINE TO THE CLAIM FOR PARTS ONLY FOR SLIDE FASCIA.

CAUSE: THE SLIDE OUT INTERIOR FASCIA IS NOT AVAIL ANY LONGER FROM FOREST RIVER. NEED TO REPLACE THE FASCIA WITH THE GRAY.

CORRECTION: REPLACE THE WHITE FASCIA WITH THE GRAY.

Parts

Part #	Description	Qty	Price	Total
F100423979	FASCIA, BLOCK HARMONY DOVE RT/LT/CT	6.00	52.14	312.84
F100546590	MLDG, CAP MLDG 1-1/4" W/3/4" LEGS BLACK 12' (BOX QTY 640) - FASCIA	60.00	1.51	90.60
F100423962	FASCIA, TOP MLDG #4628 6" X 169" MDF HARMONY DOVE	4.00	34.98	139.92
F100423960	FASCIA, LEG MLDG #4627 5" X 85" MDF HARMONY DOVE	6.00	11.97	71.82
F100546590	MLDG, CAP MLDG 1-1/4" W/3/4" LEGS BLACK 12' (BOX QTY 640) - FASCIA	48.00	1.51	72.48

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	18.99	18.99
SHP	CRATE ON S4962678	1.00	45.00	45.00
CRA	CRATE ON S4962678	1.00	470.39	470.39
SHP	SHP ON S5047154	1.00	416.03	416.03
CRA	CRATE ON S5047154	1.00	25.00	25.00

Subtotal for Job #3: 1,663.07

Parts Total:	958.33
Labour Total:	1,320.00
Sublet Total:	0.00
Extras Total:	993.84
WORK ORDER TOTAL:	3,272.17

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 01 Jul 2025

Customer Signature : _____



Customer #: 57896
ADCOX, JAMES

