



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25200



WO #: 25200

Customer: 57896 - ADCOX, JAMES
 Address: 300 CAMBY DR
 KINGSPOUR, TN
 37664
 Home Phone: 423-765-6863
 Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 10697
 Stock Desc: 2023 A FOREST RIVER MIRADA
 35OS
 Model: 35OS
 Serial #: 5ZTAMD001PM517566
 Chassis #: 1F66F5DN8M0A15656
 Mileage: 966
 Key #: 8000
 Req'n #:
 License #:
 Trim:

Purchase Date: 11 JUL 24
 Date In: 31 MAR 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date: 11 JUL 24

Job #1 - Warranty

COMPLAINT: LIVING ROOM SLIDE IS NOT GOING IN AND OUT

CAUSE: SLIDE MOTOR WILL NOT MOVE BUT DOES HAVE POWER AND GROUND GOING TO IT.
 WATER IS LEAKING FROM THE WIPER SEAL NOT BEING INSTALLED CORRECTLY FROM FACTORY.

CORRECTION: REMOVE FASCIA TO ACCESS MOTOR AND THE MECHANISM COVER TO ACCESS
 MOTOR
 REMOVE AND REPLACE THE SLIDE MOTOR
 LABOR 1.0

Parts

Part #	Description	Qty	Price	Total
C01259667	MOTOR 42 MM IN WALL SLIDE - MID TORQUE W/ BRAKE	1.00	N/C	N/C
F100220643	TAPE, SEAM MATTE LUX VELVET WHITE, 6"-	24.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: FASCIA ON LIVING ROOM SLIDE HAD TO BE REMOVED IN ORDER TO ACCESS THE
 SLIDE MOTOR. WHEN TECH REMOVED FASCIA WE FOUND WATER DAMAGE ON LEFT SIDE.

CAUSE: TOP WIPER SEAL ON SLIDE OUT ALLOWED WATER TO RUN DOWN THE SIDE DAMAGING
 THE INTERIOR FASCIA, RIM BOARD AND THE STILE PIECES IN THIS AREA.

CORRECTION: SLIDE NEEDS TO BE PULLED IN ORDER TO REMOVE AND REPLACE ALL DAMAGED
 WOOD IN THIS AREA. THIS SLIDE HOLDS A TABLE, CHAIRS AND DOUBLE SEATING THAT HAS TO
 BE R&R. CLEAN SLIDE MATERIAL TOP TO BOTTOM TO REMOVE ALL THE MOLD.
 LABOR 6.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: AS REQUESTED BY FOREST RIVER TO ADD A LINE TO THE CLAIM FOR PARTS ONLY
 FOR SLIDE FASCIA.

CAUSE: THE SLIDE OUT INTERIOR FASCIA IS NOT AVAIL ANY LONGER FROM FOREST RIVER.

Customer #: 57896
 ADCOX, JAMES



NEED TO REPLACE THE FASCIA WITH THE GRAY.

CORRECTION: REPLACE THE WHITE FASCIA WITH THE GRAY.

Subtotal for Job #3: 0.00

W/O: 25200

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 06 May 2025

Customer Signature : _____



Customer Work Order

Customer #: 57896
ADCOX, JAMES

