



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25239



WO #: 25239

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11084

Stock Desc: 2025 THTT FOREST RIVER ROGUE
26L140

Model: 26L140

Serial #: 4X4TVGB28S5403472

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 08 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 14 JUN 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: COMPARTMENT DOOR AREA ON THE FRONT OF THE UNIT HAS EXCESSIVE METAL SHAVING ON ALL SIDES OF SEALANT

CAUSE: NOTED ON DAF

CORRECTION: NEED TO REMOVE ALL SEALANT, CLEAN AREA AND RESEAL
LABOR 1.2

Labor

Job #	Description	Hours	Total
1	CLEANED AREA WITH METAL SHAVINGS	1.50	247.50

Parts

Part #	Description	Qty	Price	Total
38-1865	PROFLEX RV SEALANT BLK	2.00	12.38	24.76

Subtotal for Job #1: 272.26

Job #2 - Warranty

COMPLAINT: BLACK PRINTS ON CEILING AT PROJECTOR IN BEDROOM. MARKS ARE OVER HALF WAY ACROSS CEILING PANELS.

CAUSE: NOTED ON DAF
WHEN INSTALLED AT FACTORY AREA WAS NOT CLEANED.

CORRECTION: CLEAN ALL BLACK MARKS OFF CEILING AND PROJECTOR AREA
LABOR .30

Labor

Job #	Description	Hours	Total
2	CLEANED MARKS	0.25	41.25

Subtotal for Job #2: 41.25

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HAS SCRATCHES ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND CLEAN SCRATCHED AREA
LABOR .10

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor

Job #	Description	Hours	Total
3	FILL COLOR AND CLEAN	0.10	16.50

Subtotal for Job #3: 16.50**Job #5 - Warranty**

COMPLAINT: COMPARTMENT DOOR TO THE RIGHT OF THE ENTRY DOOR WILL NOT SHUT AT THE BOTTOM. THIS CAUSES THE DOOR TO STICK OUT AT THE BOTTOM.

CAUSE: NOTED ON DAF.

CORRECTION: ADJUST COMPARTMENT DOOR
LABOR .20

Labor

Job #	Description	Hours	Total
5	ADJUSTED COMPARTMENT DOOR	0.20	33.00

Subtotal for Job #5: 33.00**Job #6 - Warranty**

COMPLAINT: STILE AND TRACK GOING INTO THE BATHROOM IS SCRATCHED.

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND CLEAN SCRATCHED AREAS
LABOR .10

Labor

Job #	Description	Hours	Total
6	FILL AND COLOR	0.10	16.50

Subtotal for Job #6: 16.50**Job #7 - Warranty**

COMPLAINT: MICROWAVE HAS SEVERAL SCRATCHES ALL ACROSS THE FRONT AND SIDES.
MOD# OTR1603B
SER#240730024000294

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE MICROWAVE
LABOR .50

Labor

Job #	Description	Hours	Total
7	RUBBING COMPOUND APPLIED	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
13-0403	GG-16 GEL GLOSS 16OZ	1.00	9.14	9.14

Subtotal for Job #7: 42.14**Job #8 - Warranty**

COMPLAINT: HOLE FOUND IN AWNING FABRIC.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE AWNING FABRIC
LABOR 1.5



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor

Job #	Description	Hours	Total
8	REPLACED AWNING FABRIC	1.50	247.50

Parts

Part #	Description	Qty	Price	Total
F100729551	AWNING FABRIC ONLY, CO-CP/AL 216" BLK, LED	1.00	619.91	619.91

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	75.00	75.00

Subtotal for Job #8: 942.41**Job #9 - Warranty**

COMPLAINT: WHITE METAL AT REAR OF UNIT IS SCRATCHED.

CAUSE: NOTED ON DAF

CORRECTION: COLOR, FILL AND CLEAN SCRATCHED AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
9	FILL AND COLOR	0.20	33.00

Subtotal for Job #9: 33.00

Parts Total: 653.81
Labour Total: 668.25
Sublet Total: 0.00
Extras Total: 75.00

WORK ORDER TOTAL: 1,397.06

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Jun 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,