

DEALER ACCOUNT #	0049080	CLAIM STATUS	Paid
TRI AM RV CENTER OF EAST TN		CLAIM	2257173
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN	WEB
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN	4X4TVGB28S5403472
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	081 / 081A
OWNER INFORMATION		ITEM #	VGT26L140-81
		DEALER RO #	25239
		CLAIM START DATE	04/08/2025
		CLAIM END DATE	06/14/2025
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code 20-85-24-00-000862	Operational Description Paint or Repaint Any Entry, Compartment, Access Door - Exterior/Full Body Paint/Repair/No Tread Code	
	Complaint, Cause, Correction Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:47:11 :: Complaint: Compartment door area on the front of the unit has excessive metal shaving on all sides of sealant Cause: Noted on DAF Correction: Need to remove all sealant, clean area, and reseal		
Model#	Dlr Sub Hrs	1.50	Sub Labor Amt \$247.50
Serial#	Appr Hrs	1.00	Appr Labor Amt \$165.00
	Notes Authorized as Requested.		

Line# 1	Item #		Description			
	USERPART		38-1865 Proflex rv sealant blk			
	Model #		Serial #		Part tag	
	Sub Qty	2.00	Sub Dlr Price	\$24.76	Sub Freight	\$0.00
	Appr Qty	2.00	Appr Dlr Price	\$24.76	Appr Freight	\$0.00
	Notes					

Line# 2	Operation Code	Operation Description		
	30-102-24-00-003061	Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:50:24 :: Complaint: Black prints on ceiling at projector in bedroom. Marks are over half way across ceiling panels Cause: Noted on DAF Correction: Clean all black marks off ceiling and projector area			
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$49.50
	Serial#	Appr Hrs	0.25	Appr Labor Amt\$41.25
	Notes			
	Authorized as Requested.			

Line# 3	Operation Code	Operational Description		
	30-101-36-00-001076	Hinged Passage Door - Interior/Interior Doors/Touch Up/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:51:56 :: Complaint: Bathroom door has scratches on it Cause: Noted on DAF Correction: Fill, color, and clean scratched area			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.50

Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.50
Notes				
Labor				
Line# 4	Operation Code	Operational Description		
	20-69-02-00-000705	Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:54:58 :: Complaint: Compartment door to the right of the entry door will not shut at the bottom. This causes the door to stick out at the bottom. Cause: Noted on DAF Correction: Adjust compartment door			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$33.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$33.00
Notes				

Labor				
Line# 5	Operation Code	Operational Description		
	30-100-36-00-001050	Cabinet Stiles - Interior/Cabinetry/Touch Up/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:55:59 :: Complaint: Stile and track going into the bathroom is scratched Cause: Noted on DAF Correction: Fill, color, and clean areas			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.50
Notes				

Labor

Line# 6	Operation Code	Operational Description		
	70-150-24-00-002780	Greystone Microwave - Appliances/Microwave/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:56:56 :: Complaint: Microwave has several scratches all across the front and sides Cause: Noted on DAF Correction: Remove and replace the microwave			
Model#	OTR1603B	Dlr Sub Hrs	0.50	Sub Labor Amt \$82.50
Serial#	240730024000294	Appr Hrs	0.20	Appr Labor Amt \$33.00
	Notes			
	This will come off with a rubbing compound			
	We will try that, thank you.			
	Buff and polish not replace			

Part				
Line# 1	Item #	Description		
	USERPART	13-0403 GG-16 gloss 16 oz		
	Model #	Serial #	Part tag	
	Sub Qty 1.00	Sub Dlr Price \$9.14	Sub Freight	\$0.00
	Appr Qty 1.00	Appr Dlr Price \$9.14	Appr Freight	\$0.00
Notes				

Labor

Line# 7	Operation Code	Operational Description		
	20-82-01-00-000849	Awning Fabric - Exterior/Awnings (Carefree of Colorado)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-04-08 10:58:11 :: Complaint: Hole found in awning fabric			
	Cause: Noted on DAF Correction: Remove and replace awning fabric			
Model#	241230100770	Dlr Sub Hrs	1.50	Sub Labor Amt \$247.50
Serial#	1V2164E4EAWU	Appr Hrs	1.50	Appr Labor Amt \$247.50
	Notes			
	Authorized as Requested.			

Part				
Line# 2	Item #	Description		

F100729551

AWNING PARTS, FABRIC ONLY, CO-CP/AL 216" BLCK, BLK LED RL FOR
IV2164E4EAWU, IMGZ2169292AWJ (9A-ORDER) (18' FABRIC ONLY)

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$619.91

Sub Freight \$75.00

Appr Qty 1.00

Appr Dlr Price \$619.91

Appr Freight \$75.00

Notes

Labor

Line# 8

Operation Code

20-58-24-00-000608

Operational Description

Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Repair/
No Tread Code

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-04-08 11:02:11 :: Complaint: White metal at rear of unit is
scratched Cause: Noted on DAF Correction: Color, fill, and clean scratched area

Model#

Dlr Sub Hrs 0.20

Sub Labor Amt \$33.00

Serial#

Appr Hrs 0.20

Appr Labor Amt \$33.00

Notes

Authorized as Requested.

Submitted

Labor Amt \$726.00
Parts & Freight \$728.81
Total \$1,454.81

Approved

Labor Amt \$585.75
Parts & Freight \$728.81
Total \$1,314.56

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.