

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2319366
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4FCRK20PS232076
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 020 / 020
 ITEM # CRF3425RL
 DEALER RO # 25267
 CLAIM START DATE 06/02/2025
 CLAIM END DATE 06/04/2025

Labor rate: \$165.00

OWNER INFORMATION

DAVID SLACK
 540 BERKELEY DR
 Morristown, TN 37814
 USA

Retail Date of Purchase 07/27/2024 WARRANTY EXPIRATION DATE 07/27/2025

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 30-103-24-00-001125 Linoleum - Interior/Flooring/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-06-02 14:50:21 :: Complaint: Customer has spots under the lino at the fridge and pantry and recliner Cause: Lino flooring developed wrinkles Correction: Lino needs repaired. Cut lino in area and lay flat with weights on it, then add adhesive to lay flooring back into place

Model#		Dlr Sub Hrs	2.00	Sub Labor Amt	\$330.00
Serial#		Appr Hrs	2.00	Appr Labor Amt	\$330.00

Notes
 AUTHORIZED

Part

Line# 1	Item #	Description			
	USERPART	Adhesive			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$10.99	Sub Freight \$0.00		
	Appr Qty 1.00	Appr Dlr Price \$10.99	Appr Freight \$0.00		

Notes

Labor

Line# 2 Operation Code Operational Description
 24-30-101-003418 Interior Door Jam, Casing, Trim - Repair/Interior/Interior Doors
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-06-02 14:51:24 :: Complaint: Molding coming down at closet Cause: Trim was not secure and came down Correction: Resecure trim

Model#		Dlr Sub Hrs	0.30	Sub Labor Amt	\$49.50
Serial#		Appr Hrs	0.30	Appr Labor Amt	\$49.50

Notes

Submitted	Labor Amt	\$379.50	Approved	Labor Amt	\$379.50
	Parts & Freight	\$10.99		Parts & Freight	\$10.99
	Total	\$390.49		Total	\$390.49

DEALER _____ DATE _____
 SIGNATURE

CUSTOMER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.