



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25268



WO #: 25268

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11087

Stock Desc: 2025 THTT FOREST RIVER ROGUE
29SUT

Model: 29SUT

Serial #: 5NHTVGE28SC005513

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 11 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SLIDE ROOM WALL AND CEILING HAS SEVERAL SPOTS AND THIS MAKES PANEL LOOK SPOTTED

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND SPOTS

LABOR .20

Subtotal for Job #1: 0.00

Job #3 - Warranty

COMPLAINT: GENERATOR COMPARTMENT DOOR HAS DEEP SCRATCHES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR

LABOR 1.0

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: COMPARTMENT DOOR TRIM IS SCRATCHED IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND TRIM

LABOR .20

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: FURRION COVER ON CEILING (A/C) IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE A/C COVER ON THE INTERIOR

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #5: 0.00**Job #6 - Warranty**

COMPLAINT: INTERIOR DOOR HAS SCUFS ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: RAMP DOOR HAS DAYLIGHT COMING IN AROUND UPPER RIGHT AND LEFT CORNERS

CAUSE: NOTED ON DAF
SEAL AROUND THE RAMP DOOR WAS CUT TO SHORT AND LEAVING A GAP ON BOTH SIDESCORRECTION: SEAL NEEDS REPLACED ON BOTH SIDES TO MEET AND SEAL CORRECTLY.
LABOR 2.0**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: SLIDE OUT WALL HAS WHITE SPOTS AND A LINE THAT NEEDS BLENDED

CAUSE: NOTED ON DAF

CORRECTION: BLEND AND COLOR AREA
LABOR .20**Subtotal for Job #8: 0.00****Job #9 - Warranty**

COMPLAINT: SCREWS IN CABINET BESIDE THE FRIDGE ARE COMING THROUGH THE SIDES

CAUSE: NOTED ON DAF
SCREWS USED WERE TO LONGCORRECTION: REMOVE SCREWS,FILL HOLES AND REINSTALL WITH SHORTER SCREWS.
LABOR .30**Subtotal for Job #9: 0.00****Job #10 - Warranty**

COMPLAINT: KITCHEN CABINET SCRATCHED AND CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR,BLEND AND CLEAN THE AREA
LABOR .20**Subtotal for Job #10: 0.00****Job #11 - Warranty**

COMPLAINT: INTERIOR WALL GOING INTO THE BEDROOM HAS SPOTS THAT WAS NOT BLENDED AFTER FILLED

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CAUSE: NOTED ON DAF

CORRECTION: BLEND AND COLOR THE AREA
LABOR .20

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: PARTY DECK FENCE ONLY HAS ONE STRAP

CAUSE: NOTED ON DAF

CORRECTION: REPLACE ONE STRAP ON PARTY DECK
* THIS MAY ONLY REQUIRE ONE STRAP *
LABOR .05

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: WINDOW AND TRIM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE WINDOW AND WATER TEST
LABOR 1.0

Subtotal for Job #13: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Apr 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,