



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25268



WO #: 25268

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11087

Stock Desc: 2025 THTT FOREST RIVER ROGUE
29SUT

Model: 29SUT

Serial #: 5NHTVGE28SC005513

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 11 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 20 MAY 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: SLIDE ROOM WALL AND CEILING HAS SEVERAL SPOTS AND THIS MAKES PANEL
LOOK SPOTTED

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND SPOTS

LABOR .20

Labor

Job #	Description	Hours	Total
1	CLEANED	0.20	33.00
Subtotal for Job #1:			33.00

Job #3 - Warranty

COMPLAINT: GENERATOR COMPARTMENT DOOR HAS DEEP SCRATCHES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR

LABOR 1.0

Labor

Job #	Description	Hours	Total
3	BUFF OUT	0.50	82.50
Subtotal for Job #3:			82.50

Job #4 - Warranty

COMPLAINT: COMPARTMENT DOOR TRIM IS SCRATCHED IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND TRIM

LABOR .20

Labor

Job #	Description	Hours	Total
4	TOUCHED UP PAINT	0.20	33.00

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 33.00

Job #5 - Warranty

COMPLAINT: FURRION COVER ON CEILING (A/C) IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE A/C COVER ON THE INTERIOR
LABOR .20**Labor**

Job #	Description	Hours	Total
5	REPLACED COVER	0.10	16.50

Parts

Part #	Description	Qty	Price	Total
F100693219	FURRION ELEC AIR DISTRIBUTION BOX	1.00	59.36	59.36

Subtotal for Job #5: 75.86

Job #6 - Warranty

COMPLAINT: INTERIOR DOOR HAS SCUFS ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
6	TOUCH UP	0.20	33.00

Subtotal for Job #6: 33.00

Job #7 - Warranty

COMPLAINT: RAMP DOOR HAS DAYLIGHT COMING IN AROUND UPPER RIGHT AND LEFT CORNERS

CAUSE: NOTED ON DAF

SEAL AROUND THE RAMP DOOR WAS CUT TO SHORT AND LEAVING A GAP ON BOTH SIDES

CORRECTION: SEAL NEEDS REPLACED ON BOTH SIDES TO MEET AND SEAL CORRECTLY.
LABOR 2.0**Labor**

Job #	Description	Hours	Total
7	REPLACED SEAL	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100694808	SEAL, 5/8" X 25FT SLIDE OUT LG BULB "D" SEAL SELF ADHESIVE - BLACK	1.00	40.76	40.76

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	13.47	13.47
SHF	SHIPPING/FREIGHT FEE	1.00	18.46	18.46

Subtotal for Job #7: 237.69

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Job #8 - Warranty

COMPLAINT: SLIDE OUT WALL HAS WHITE SPOTS AND A LINE THAT NEEDS BLENDED

CAUSE: NOTED ON DAF

CORRECTION: BLEND AND COLOR AREA

LABOR .20

Labor

Job #	Description	Hours	Total
8	BLENDED AREA	0.20	33.00

Subtotal for Job #8: 33.00**Job #9 - Warranty**

COMPLAINT: SCREWS IN CABINET BESIDE THE FRIDGE ARE COMING THROUGH THE SIDES

CAUSE: NOTED ON DAF

SCREWS USED WERE TO LONG

CORRECTION: REMOVE SCREWS,FILL HOLES AND REINSTALL WITH SHORTER SCREWS.

LABOR .30

Labor

Job #	Description	Hours	Total
9	REPAIRED AREA	0.20	33.00

Subtotal for Job #9: 33.00**Job #10 - Warranty**

COMPLAINT: KITCHEN CABINET SCRATCHED AND CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR,BLEND AND CLEAN THE AREA

LABOR .20

Labor

Job #	Description	Hours	Total
10	BLENDED AND CLEANED	0.30	49.50

Subtotal for Job #10: 49.50**Job #11 - Warranty**

COMPLAINT: INTERIOR WALL GOING INTO THE BEDROOM HAS SPOTS THAT WAS NOT BLENDED AFTER FILLED

CAUSE: NOTED ON DAF

CORRECTION: BLEND AND COLOR THE AREA

LABOR .20

Labor

Job #	Description	Hours	Total
11	BLENDED AREA	0.20	33.00

Subtotal for Job #11: 33.00**Job #12 - Warranty**

COMPLAINT: PARTY DECK FENCE ONLY HAS ONE STRAP

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CAUSE: NOTED ON DAF

CORRECTION: REPLACE ONE STRAP ON PARTY DECK

* THIS MAY ONLY REQUIRE ONE STRAP *

LABOR .05

Labor

Job #	Description	Hours	Total
12	REPLACED STRAP	0.05	8.25

Subtotal for Job #12: 8.25**Job #13 - Warranty**

COMPLAINT: WINDOW AND TRIM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE WINDOW AND WATER TEST

LABOR 1.0

Labor

Job #	Description	Hours	Total
13	REPAIRED AREA	0.50	82.50

Subtotal for Job #13: 82.50

Parts Total:	100.12
Labour Total:	602.25
Sublet Total:	0.00
Extras Total:	31.93

WORK ORDER TOTAL: 734.30

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 20 May 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,