



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25291



WO #: 25291

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11092

Stock Desc: 2025 TT KZ-RV CONNECT 313MK

Model: 313MK

Serial #: 4EZTL3322S4035555

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 16 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SEALANT IN FOUR SPOTS ON THE EXTERIOR DOOR SIDE OF THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: SEALANT NEEDS TO BE CLEANED OFF, WASHING THE UNIT AS NORMAL DID NOT REMOVE THE SEALANT.

LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHADE OVER DOUBLE SEATING IN THE REAR OF UNIT WAS LAYING DOWN WHEN ARRIVED TO DEALER.

CAUSE: NOTED ON DAF

CORRECTION: INSTALL SHADE AND TEST

LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: FURRIOR STOVE VENT IS SIDEWAYS, NOT INSTALLED CORRECTLY AT BUILD TIME.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND INSTALL THE STOVE VENT COVER CORRECTLY.

LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: VALANCE OVER SEATING IN LIVING AREA IS NOT SECURED TO THE WALL.

CAUSE: NOTED ON DAF.

CORRECTION: RESECURE THE VALANCE TO THE WALL.

LABOR .10

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: STILE OVER LIVING AREA SEATING HAS HOLES IN IT.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR,BLEND AND CLEAN AREA.
LABOR .10**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: RIGHT SIDE (IF SITTING ON SEATING) WILL NOT GO IN OR OUT WITHOUT FORCE.

CAUSE: INTERNAL MECHANISM IS FAULTY AND WILL NOT ALLOW THE FOOT REST TO WORK
CORRECTLY. NOTED ON DAF.CORRECTION: RIGHT SIDE OF RECLINER SEATING NEEDS REPALCED.
LABOR .50**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: BLACK MARKS ON THE WALL ABOVE THE SHOWER SURROUND.

CAUSE: NOTED ON DAF.

CORRECTION: CLEAN OFF THE BLACK MARKS. COLOR AND BLEND AREA IF NEEDED.
LABOR .10**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: DOOR FACING GOING INTO THE BEDROOM HAS BLACK MARKS.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN OFF ALL BLACK MARKS. COLOR AND BLEND AREA.
LABOR .10**Subtotal for Job #8: 0.00****Job #9 - Warranty**COMPLAINT: BEDROOM DOOR IS ROUGH ALL THE WAY DOWN THE SIDE AND DENTED IN ONE
AREA ON THE SIDE. THIS DOOR ALSO HAS SEVERAL SCRATCHES. DOOR FACING STILE IS
CHIPPED AS WELL.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE BEDROOM DOOR AND STILE THAT IS CHIPPED.
LABOR 1.2**Subtotal for Job #9: 0.00****Job #10 - Warranty**COMPLAINT: STILE GOING INTO THE BEDROOM CLOSET HAS TWO SPOTS THAT NEED TO BE
BLENDED.Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND THE AREA.
LABOR .10

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: BEDROOM DRAWER IS CHIPPED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND CLEAN THE CHIPPED AREA.
LABOR .10

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: LINO FLOORING HAS FOUR DIFFERENT HOLES AND A SMALL TEAR NEAR THE
EENTRY DOOR. THESE HOLES ARE TO THE LEFT AND THE RIGHT.

CAUSE: NOTED ON DAF

CORRECTION: DAMAGED LINO NEEDS TO BE REMOVED AND REPLACED WITH NEW.
LABOR 6.0

Subtotal for Job #12: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 16 Apr 2025

W/O: 25291



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

