

**Claim Response**

**Claim: C3798017**

**Non-Warranty Goodwill Adjustment**

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3798017	25303	4/18/2025	4/21/2025	4YDT33023M1532587	PA03840707	8140	Tri-AM RV Center of East TN 1202 Idell Rd Bulls Gap, TN 37711	175.00	0.00	POL	7/8/2021

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
6201106B	Regulator - Replace	Complaint: On C3723113 we were approved to perform LP regulator and pigtail recall. The labor was paid, but no parts were added to the claim. This is for the parts and shipping only Cause: Recall Correction: Recall complete, parts and shipping cost only  KRV-approved parts & shipping cost only	Inspection only approved on C3723113*** per Shelby email ***			0.00	51.13	1	0.30	Approved

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	51.13	Approved labor & subLet	51.13
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
<b>Total Submitted:</b>	<b>51.13</b>	<b>Total approved:</b>	<b>51.13</b>