



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 25321

Customer: 72736 - HICKMAN, MARK
Address: 3103 MARCUM DR
MORRISTOWN, TN
37814
Home Phone: (423) 273-0005
Work Phone:
Author: SPD
Location: IH
Invoice #: 418446

Stock #: 10879
Stock Desc: 2024 FW FOREST RIVER CEDAR
CREEK 371FL
Model: 371FL
Serial #: 4X4FCRN25RS232718
Chassis #:
Mileage:
Key #: 9500
Req'n #:
License #:
Trim:

Purchase Date: 06 JUN 24
Date In: 22 APR 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 20 MAY 25
Warr. Date: 06 JUN 24

Job #1 - Warranty

COMPLAINT: CUSTOMER COMPLAINED THE BLACK TANK HANDLE IS NOT CLOSING.

CAUSE: FOUND THE BLACK TANK HANDLE IS BENT NOT ALLOWING THE PROPER FUNCTION OF HANDLE.

CORRECTION: R&R BLACK TANK HANDLE,
LABOR .30

Labor

Job #	Description	Hours	Total
1	MISC. LABOR CODE	0.30	49.50

Parts

Part #	Description	Qty	Price	Total
60P10689A	DUMP VALVE 3" BRISTOL	1.00	57.51	57.51

Subtotal for Job #1: 107.01

Job #2 - Warranty

COMPLAINT: MOTION LIGHT IN THE BATHROOM IS FLICKERING.

CAUSE: MOTION LIGHT IS NOT STAYING ON AND IS FLICKERING.

CORRECTION: REMOVE AND REPLACE THE MOTION LIGHT,
LABOR .20

Labor

Job #	Description	Hours	Total
2	REPLACED LIGHT	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
F100439004	LIGHT, MOTION, 12V LED, AISLE/ACCENT LIGHT W/MOTION SENSOR, BLACK	1.00	6.11	6.11

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	18.41	18.41

Subtotal for Job #2: 57.52

W/O: 25321

Customer #: 72736
HICKMAN, MARK

Job #3 - Warranty

COMPLAINT: MOTION LIGHT NEAR THE ENTRANCE STEP IS ALSO FLICKERING AND DOES NOT STAY ON AS IT SHOULD.

CAUSE: MOTION LIGHT IS NOT STAYING ON AND IS FLICKERING.

CORRECTION: REMOVE AND REPLACE THE MOTION LIGHT AT ENTRANCE,
LABOR .20

Labor

Job #	Description	Hours	Total
3	REPLACED LIGHT	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
F100439004	LIGHT, MOTION, 12V LED, AISLE/ACCENT LIGHT W/MOTION SENSOR, BLACK	1.00	6.11	6.11

Subtotal for Job #3: 39.11

Job #4 - External

COMPLAINT: INSTALL TANK HANDLE EXTENSIONS ON BOTH BLACK AND 1 GRAY HANDLE. CUST DOES NOT WANT ONE ON THE GRAY TANK HANDLE NEAR WHEEL WELL

CORRECTION: INSTALL TANK HANDLE EXTENSIONS ON 3 TANKS AT CUSTOMERS REQUEST.

Labor

Job #	Description	Hours	Total
4	INSTALL EXT	0.50	N/C

Subtotal for Job #4: 0.00

Parts Total: 69.73
Labour Total: 115.50
Sublet Total: 0.00
Extras Total: 18.41

WORK ORDER TOTAL: 203.64

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 20 May 2025

Customer #: 72736
HICKMAN, MARK