



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25323



WO #: 25323

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11091

Stock Desc: 2025 TT KZ-RV CONNECT 312RE

Model: 312RE

Serial #: 4EZTL3321S4035577

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 22 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: CEILING LIGHT IN LIGHT AREA ON FLOOR AND COVER WILL NOT STAY ON.

CAUSE: NOTED ON DAF

CORRECTION: R&R CEILING LIGHT AND TEST
LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHADE TO LEFT OF THE SEATING (DS) WILL NOT RETRACT UP AND TECH IS NOT ABLE TO ADJUST.

CAUSE: NOTED ON DAF
SHADE IS FAULTY

CORRECTION: R&R SHADE AND TEST
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: STAPLE HOLES IN STILE BOARD AT THE SOUND BAR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SMALL HOLE IN WALL ON DS SLIDE IN THE LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: STILE OVER DS SLIDE HAS NAIL/STAPLE HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: CHIP ON TOP OF BATHROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: R&R BATHROOM DOOR
LABOR .50**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: STILE OVER SEATING HAS CHIPS ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: CHIP IN BEDROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND
LABOR .20**Subtotal for Job #8: 0.00****Job #9 - Warranty**

COMPLAINT: HOLE IN LINO AT THE ENTRY DOOR

CAUSE: NOTED ON DAF

CORRECTION: REPAIR HOLE AND NOTE TO UNIT FOR FUTURE
LABOR 2.0**Subtotal for Job #9: 0.00****Job #10 - Warranty**

COMPLAINT: BATHROOM CORNER TRIM HAS PUDDY COMING OUT FROM BEHIND IT.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND BLEND AREA
LABOR .10Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #10: 0.00**Job #11 - Warranty**

COMPLAINT: BATHROOM CABINET DOOR HAS BLACK MARKS ON THE CORNER

CAUSE: NOTED ON DAF

CORRECTION: COLOR,CLEAN AND BLEND THE AREA
LABOR .20**Subtotal for Job #11: 0.00****Job #12 - Warranty**

COMPLAINT: BATHROOM CABINET DOOR HANDLE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE HANDLE
LABOR .20**Subtotal for Job #12: 0.00****Job #13 - Warranty**

COMPLAINT: BATHROOM DOOR CASING HAS A GAP ON THE ONE SIDE OF IT IN THE CORNER

CAUSE: NOTED ON DAF

CORRECTION: R&R THE BATHROOM DOOR CASING, GAP IS TO LARGE TO FILL AND LOOK LIKE
THE OTHER SIDE.
LABOR 1.0**Subtotal for Job #13: 0.00****Job #14 - Warranty**

COMPLAINT: J WRAP ON DOOR SIDE STICKING OUT, MISSING SCREW AND SEALNT

CAUSE: NOTED ON DAF

CORRECTION: RESECURE THE J WRAP BY ADDING SCREW AND RESEAL THE AREA
LABOR .50**Subtotal for Job #14: 0.00**Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Customer Signature : _____

Date: 22 Apr 2025

W/O: 25323



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

