



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25323



WO #: 25323

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11091

Stock Desc: 2025 TT KZ-RV CONNECT 312RE

Model: 312RE

Serial #: 4EZTL3321S4035577

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 22 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 21 MAY 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: CEILING LIGHT IN LIGHT AREA ON FLOOR AND COVER WILL NOT STAY ON.

CAUSE: NOTED ON DAF

CORRECTION: R&R CEILING LIGHT AND TEST

LABOR .30

Labor

Job #	Description	Hours	Total
1	REPLACED LIGHT	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
156558	LIGHT,CEILING,MUSHROOM,LED,WIT H HARD SWITCH,4 1/2",4000K,200/BOX	1.00	1.99	1.99

Subtotal for Job #1: 36.99

Job #2 - Warranty

COMPLAINT: SHADE TO LEFT OF THE SEATING (DS) WILL NOT RETRACT UP AND TECH IS NOT ABLE TO ADJUST.

CAUSE: NOTED ON DAF

SHADE IS FAULTY

CORRECTION: R&R SHADE AND TEST

LABOR .30

Labor

Job #	Description	Hours	Total
2	REPLACE SHADE	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
162738	SHADE,ROLLER,DARK CHARCOAL,BASELINE,IMPORT,17MM ,26X32	1.00	38.36	38.36

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	16.43	16.43

Subtotal for Job #2: 72.29

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Job #3 - Warranty

COMPLAINT: STAPLE HOLES IN STILE BOARD AT THE SOUND BAR

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #3: 0.00****Job #4 - Warranty**

COMPLAINT: SMALL HOLE IN WALL ON DS SLIDE IN THE LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
4	FILL AND COLOR	0.05	8.75

Subtotal for Job #4: 8.75**Job #5 - Warranty**

COMPLAINT: STILE OVER DS SLIDE HAS NAIL/STAPLE HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: CHIP ON TOP OF BATHROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: R&R BATHROOM DOOR
LABOR .50**Labor**

Job #	Description	Hours	Total
6	TOUCH UP	0.10	17.50

Subtotal for Job #6: 17.50**Job #7 - Warranty**

COMPLAINT: STILE OVER SEATING HAS CHIPS ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: CHIP IN BEDROOM DOOR

CAUSE: NOTED ON DAF

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CORRECTION: FILL,COLOR AND BLEND
LABOR .20

Labor

Job #	Description	Hours	Total
8	FILL COLOR AND BLEND	0.10	17.50

Subtotal for Job #8: 17.50

Job #9 - Warranty

COMPLAINT: HOLE IN LINO AT THE ENTRY DOOR

CAUSE: NOTED ON DAF

CORRECTION: REPAIR HOLE AND NOTE TO UNIT FOR FUTURE
LABOR 2.0

Labor

Job #	Description	Hours	Total
9	REPAIRED AND NOTED FOR FUTURE	0.50	87.50

Subtotal for Job #9: 87.50

Job #10 - Warranty

COMPLAINT: BATHROOM CORNER TRIM HAS PUDDY COMING OUT FROM BEHIND IT.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND BLEND AREA
LABOR .10

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: BATHROOM CABINET DOOR HAS BLACK MARKS ON THE CORNER

CAUSE: NOTED ON DAF

CORRECTION: COLOR,CLEAN AND BLEND THE AREA
LABOR .20

Labor

Job #	Description	Hours	Total
11	COLOR CLEAN AND BLEND	0.05	8.75

Subtotal for Job #11: 8.75

Job #12 - Warranty

COMPLAINT: BATHROOM CABINET DOOR HANDLE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE HANDLE
LABOR .20

Labor

Job #	Description	Hours	Total
12	REPLACE HANDLE	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
165976	PULL,BAR,ANTIQUE SILVER FEET & MATTE BLACK,128MM	1.00	7.87	7.87

W/O: 25323



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #12: 25.37

Job #13 - Warranty

COMPLAINT: BATHROOM DOOR CASING HAS A GAP ON THE ONE SIDE OF IT IN THE CORNER

CAUSE: NOTED ON DAF

CORRECTION: R&R THE BATHROOM DOOR CASING, GAP IS TO LARGE TO FILL AND LOOK LIKE THE OTHER SIDE.

LABOR 1.0

Labor			
Job #	Description	Hours	Total
13	FILL AND COLOR	0.10	17.50
Subtotal for Job #13:			17.50

Job #14 - Warranty

COMPLAINT: J WRAP ON DOOR SIDE STICKING OUT, MISSING SCREW AND SEALNT

CAUSE: NOTED ON DAF

CORRECTION: RESECURE THE J WRAP BY ADDING SCREW AND RESEAL THE AREA

LABOR .50

Labor			
Job #	Description	Hours	Total
14	RESECURE AND ADD SCREW	0.20	35.00
Subtotal for Job #14:			35.00

Parts Total:	48.22
Labour Total:	262.50
Sublet Total:	0.00
Extras Total:	16.43
WORK ORDER TOTAL:	327.15


I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 May 2025

W/O: 25323



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

