



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25324
Promised Date:
22 APR 25



Customer #: 88582
PRUETT, EDWARD



WO #: 25324 (Appointment Date: 22 APR 2025 - Time: 01:00pm)

Customer: 88582 - PRUETT, EDWARD
Address: 1114 ARTHUR RD
JEFFERSON CITY, TN
37760

Home Phone: 423-327-0956

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10855

Stock Desc: (10855) 2024 FOREST RIVER

FORESTER 3051SF

Model: 3051SF

Serial #: 1FDXE4FN7RDD23859

Chassis #: 1FDXE4FN7RDD23859

Mileage:4683

Key #: 6999

Req'n #:

License #:

Trim:

Purchase Date: 06 DEC 23

Date In: 22 APR 25

Promise Date: 22 APR 25

Promise Time: 09:00am

Schedule Date:

Completed: 27 MAY 25

Warr. Date: 06 DEC 23

Job #1 - Warranty

COMPLAINT: SKYLIGHT NUM 1 FRONT DRIVER SIDE IS CRACKED.

CAUSE: SERV BULLETIN 34-1893

CORRECTION: REPLACE THE FRONT DRIVER SIDE SKYLIGHT
LABOR 1.0

Labor

Job #	Description	Hours	Total
1	REPLACED SKYLIGHT	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100716954	TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT	1.00	64.86	64.86
38-9018	LAP SEALANT WHITE	3.00	10.21	30.63
79233	BUTYL TAPE 1/8X3/4	1.00	9.67	9.67

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
SHP	SHIPPING/FREIGHT FEE	1.00	45.68	45.68

Subtotal for Job #1: 315.84

Job #2 - Warranty

COMPLAINT: SKYLIGHT NUM 2 DRIVER SIDE REAR IS CRACKING

CAUSE: SERV BULLETIN 34-1893

CORRECTION: REPLACE THE REAR DRIVER SIDE SKYLIGHT
LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPALCED SKYLIGHT	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100716954	TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT	1.00	64.86	64.86
38-9018	LAP SEALANT WHITE	3.00	10.21	30.63



Subtotal for Job #2: 260.49

Job #3 - Warranty

COMPLAINT: SKYLIGHT NUM 3 PASSENGER SIDE IS CRACKED.

CAUSE: SERV BULLETIN 34-1893

CORRECTION: REPLACE THE SKYLIGHT REAR PASSENGER SIDE
LABOR 1.0

Labor

Job #	Description	Hours	Total
3	REPLACED SKYLIGHT	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100716954	TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT	1.00	64.86	64.86
38-9018	LAP SEALANT WHITE	3.00	10.21	30.63

Subtotal for Job #3: 260.49

Parts Total: 296.14
Labour Total: 495.00
Sublet Total: 0.00
Extras Total: 45.68

WORK ORDER TOTAL: 836.82

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 27 May 2025

W/O: 25324
Promised Date: 22 APR 25



Customer #: 88582
PRUETT, EDWARD

