

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0049080	CLAIM STATUS	Paid
TRI AM RV CENTER OF EAST TN		CLAIM	2272661
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN	WEB
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN	4X4MFRG26RF063720
		CHASSIS VIN	1FDXE4FN7RDD23859
		MILEAGE	4683
Labor rate:	\$165.00	SITE/WAREHOUSE	034 / 034A
OWNER INFORMATION		ITEM #	FRC3051SF
EDWARD PRUETT		DEALER RO #	25324
1114 ARTHUR RD		CLAIM START DATE	04/22/2025
Jefferson City, TN 37760		CLAIM END DATE	05/27/2025
USA			
Retail Date of Purchase	12/06/2023	WARRANTY EXPIRATION DATE	12/06/2024

Claim Line Details

Labor						
Line# 1	Operation Code		Operational Description			
	SB-460-01-00-004691		34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION AND REMEDY - Technical Service Bulletin/Skylights/Replace/No Tread Code			
	Complaint, Cause, Correction					
	Original Note : ashlee@dealer-advisors.com, 2025-04-22 13:00:36 :: Complaint: Skylight number 1 front driver side is cracked Cause: Service bulletin 34-1893 Correction: Replace the front drivers side skylight labor					
Model#		Dlr Sub Hrs	1.00	Sub Labor Amt	\$165.00	
Serial#		Appr Hrs	1.00	Appr Labor Amt	\$165.00	
	Notes					
	NOVCB					
Part						
Line# 1	Item #		Description			
	USERPART		Butyl Tape 1/8x3/4			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$9.67	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$9.67	Appr Freight	\$0.00
	Notes					
Line# 2	Item #		Description			
	USERPART		Lap sealant, white			
	Model #		Serial #		Part tag	
	Sub Qty	3.00	Sub Dlr Price	\$30.63	Sub Freight	\$0.00
	Appr Qty	3.00	Appr Dlr Price	\$30.63	Appr Freight	\$0.00
	Notes					
Line# 4	Item #		Description			
	F100716954		TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT (2230031252), (1) ROLL OF 1/8" BUTYL TAPE (Q13018-34), (40) SCREWS (8Z100SQP0G/P638), (4) TUBES OF DICOR 502LSW SEAL ****KIT CAN ONLY BE SOLD FOR TSB QUALIFYING UNITS*****			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$64.86	Sub Freight	\$45.68
	Appr Qty	1.00	Appr Dlr Price	\$64.86	Appr Freight	\$45.68
	Notes					

Labor

Line# 2	Operation Code		Operational Description					
	SB-460-01-00-004691		34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION AND REMEDY - Technical Service Bulletin/Skylights/Replace/No Tread Code					
Complaint, Cause, Correction								
Original Note : ashlee@dealer-advisors.com, 2025-04-22 13:02:03 :: Complaint: Skylight number 2 driver side rear is cracking Cause: Service bulletin 34-1893 Correction: Replace the rear driver side skylight								
Model#	Dlr Sub Hrs		1.00	Sub Labor Amt \$165.00				
Serial#	Appr Hrs		1.00	Appr Labor Amt \$165.00				
Notes								
NOVCB								

Part Line# 1	Item #		Description	
	F100716954		TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT (2230031252), (1) ROLL OF 1/8" BUTYL TAPE (Q13018-34), (40) SCREWS (8Z100SQP0G/P638), (4) TUBES OF DICOR 502LSW SEAL ****KIT CAN ONLY BE SOLD FOR TSB QUALIFYING UNITS*****	
Model #		Serial #		Part tag
Sub Qty		Sub Dlr Price		Sub Freight
Appr Qty		Appr Dlr Price		Appr Freight
1.00		\$64.86		\$0.00
1.00		\$64.86		\$0.00
Notes				

Line# 2	Item #		Description	
	USERPART		Lap sealant, white	
Model #		Serial #		Part tag
Sub Qty		Sub Dlr Price		Sub Freight
Appr Qty		Appr Dlr Price		Appr Freight
3.00		\$30.63		\$0.00
3.00		\$30.63		\$0.00
Notes				

Labor Line# 3	Operation Code		Operational Description					
	SB-460-01-00-004691		34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION AND REMEDY - Technical Service Bulletin/Skylights/Replace/No Tread Code					
Complaint, Cause, Correction								
Original Note : ashlee@dealer-advisors.com, 2025-04-22 13:03:20 :: Complaint: Skylight number 3 passenger side is cracked Cause: Service bulletin 34-1893 Correction: Replace the skylight rear passenger side								
Model#	Dlr Sub Hrs		1.00	Sub Labor Amt \$165.00				
Serial#	Appr Hrs		1.00	Appr Labor Amt \$165.00				
Notes								
NOVCB								
PLEASE SEND A PICTURE WHERE ALL THREE SKYLIGHTS SHOW, PLEASE								
Picture added, thank you!								

Part Line# 1	Item #		Description	
	F100716954		TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT (2230031252), (1) ROLL OF 1/8" BUTYL TAPE (Q13018-34), (40) SCREWS (8Z100SQP0G/P638), (4) TUBES OF DICOR 502LSW SEAL ****KIT CAN ONLY BE SOLD FOR TSB QUALIFYING UNITS*****	
Model #		Serial #		Part tag
Sub Qty		Sub Dlr Price		Sub Freight
Appr Qty		Appr Dlr Price		Appr Freight
1.00		\$64.86		\$0.00
1.00		\$64.86		\$0.00
Notes				

Line# 2	Item #		Description	
	USERPART		Lap sealant, white	
Model #		Serial #		Part tag
Sub Qty		Sub Dlr Price		Sub Freight
Appr Qty		Appr Dlr Price		Appr Freight
3.00		\$30.63		\$0.00
3.00		\$30.63		\$0.00

Notes

Submitted	Labor Amt	\$495.00	Approved	Labor Amt	\$495.00
	Parts & Freight	\$341.82		Parts & Freight	\$341.82
	Total	\$836.82		Total	\$836.82

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	