



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25370
 Promised Date: 30 APR 25



WO #: 25370 (Appointment Date: 30 APR 2025 - Time: 01:00pm)

Customer: 91325 - MUSE, PATRICK
 Address: 373 TRIMONT TRAIL APT 5
 FRANKLIN, NC
 28734

Home Phone: 828-371-5461

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10922

Stock Desc: (10922) 2024 KZ-RV CONNECT

302FBK

Model: 302FBK

Serial #: 4EZTL3222R4030335

Chassis #:

Mileage:0

Key #: 9690

Req'n #:

License #:

Trim:

Purchase Date: 10 DEC 24

Date In: 30 APR 25

Promise Date: 30 APR 25

Promise Time: 09:00am

Schedule Date:

Completed: 13 JUN 25

Warr. Date: 10 DEC 24

Job #1 - Warranty

COMPLAINT: AWNING WILL NOT ROLL UP AS DESIGNED TO DO. ALSO, THE FABRIC IS CROOKED AND STRETCHED.

CAUSE: IDLER ARM ON AWNING HARDWARE IS BECOME FAULTY AND ROLLED UP CROOKED. WHEN THE AWNING DIDNT ROLL UP CORRECTLY IT STRETCHED THE MATERIAL.

CORRECTION: REMOVE AND REPLACE THE COMPLETE AWNING, HARDWARE AND FABRIC.
 LABOR 1.5

Labor

Job #	Description	Hours	Total
1	REPLACED AWNING FABRIC	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
504338	AWNING,FABRIC ONLY FOR PN 143227 PWR PREFLEX BLK FADE TO WHT, 20' LIPPERT	1.00	294.46	294.46

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
SHP	SHIPPING/FREIGHT FEE	1.00	13.54	13.54

Subtotal for Job #1: 570.50

Job #2 - Warranty

COMPLAINT: CS THAT THERE IS A DOOR THAT WONT STAY CLOSED BATHROOM DOOR.

CAUSE: HINGE NEEDED TO BE ADJUSTED ON DOOR.

CORRECTION: TECH ADJUSTED HINGE AND DOOR OPENS AND CLOSSES CORRECTLY.
 LABOR .20

Labor

Job #	Description	Hours	Total
2	ADJUSTED DOOR HINGE	0.20	35.00

Customer #: 91325
 MUSE, PATRICK



Subtotal for Job #2: 35.00

W/O: 25370
Promised Date: 30 APR 25

Job #3 - Warranty

COMPLAINT: CS THAT THE THERE ARE SCREWS COMING OUT OF THE FENDER SKIRT ON DOOR SIDE CHECK THE FENDERSKIRT

CAUSE: SCREW CAME OUT OF FENDER AND THIS ALLOWED THE FENDER TO BECOME CRACKED.

CORRECTION: REPLACE THE FENDER SKIRT AND RESEAL THE AREA.
LABOR .20

Labor

Job #	Description	Hours	Total
3	REPLACED THE FENDER SKIRT	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
154817	DECAL, LOGO, KZ, RV FENDER SKIRT, CAPPED	1.00	9.81	9.81
135281	FENDERSKIRT, TANDEM, BLACK, W/O LOGO, 69X11	1.00	65.65	65.65
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	9.07	9.07

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	111.62	111.62

Subtotal for Job #3: 231.15

Customer Order Work

Parts Total:	378.99
Labour Total:	332.50
Sublet Total:	0.00
Extras Total:	125.16
WORK ORDER TOTAL:	836.65

Customer #: 91325
MUSE, PATRICK

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 18 Jun 2025

Customer Signature : _____

