

WARRANTY CLAIM # KZ605508	JOB OPERATION 3	Customer said there are screws coming out of the fender skirt on door side, check the fender skirt	OPERATION CODE 2281	AUTHORIZATION # JS5051617
			HOURS 0.20	AMOUNT \$35.00

CAUSE Screw came out of fender and this allowed the fender to become cracked	SUPPLIER NAME A KZ WARRANTY	STATUS Submitted			
	LABOR \$35.00	PARTS	MARK UP	FREIGHT	SUBLET
	PART #	CHARGEBACK # AKZ004_000605	Dup N		
	JOB OPERATION DENIAL CODE	INITIALS			
REMEDY Replace the fender skirt and reseal the area					

PART NUMBER	PART DESCRIPTION	RETURN TAG #	QUANTITY	UNIT	TOTAL PARTS	ADJUSTED TOTAL
135281	FENDERSKIRT,TANDEM,W/O LOGO,BLACK,69X11,M11FSP69BBL,**REPLACEMENT FOR 135186**		1	\$57.09	\$57.09	\$65.65
154817	DECAL,LOGO,KZ RECREATIONAL VEHICLE,FENDER SKIRT,CAPPED		1	\$8.53	\$8.53	\$9.81
38-1870	Proflex sealant CLR 10oz		1	\$9.07	\$9.07	\$10.43
SUB-TOTAL:			LABOR	\$35.00	PARTS	\$74.69

COMMENTS JS 5/16/25 Line 1 authorization is for fabric replacement only. JS 5/15/25 emailed vendor the attached "requested" photos JS 5/14/25 JS 5/12/25 JS 5/5/25 JS 5/2/25 Line 1 email sent to vendor.....Case #5828827	SUBMIT DATE 6/18/2025	TOTAL PARTS	\$330.74	\$380.35
	PREPARED BY Ashlee Olsen	MARK UP ALLOWANCE	\$49.61	
		FREIGHT	\$125.16	
		GST		
		BROKERAGE		
		TOTAL LABOR	\$332.50	
		SUBLET	\$0.00	
		TOTAL	\$838.01	\$838.01

TERMS AND CONDITIONS I hereby authorize you to perform this service at your regular prices and terms. You may operate my auto, trailer, or motor home to test, inspect or deliver same at my risk. I agree that you assume no liability for loss or damage to my trailer, auto, or motor home or the contents of either from any cause not the direct fault of your company.	I acknowledge that the services listed above have been completed, and to the extent they may be covered under warranty, I authorize KZRV, LP. to make payments to the servicing dealer.
AUTHORIZED BY _____	_____