



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25389



WO #: 25389 (Appointment Date: 05 MAY 2025 - Time: 09:00am)

Customer: 92565 - CAMPBELL, BRET
Address: 156 LINK RD
COTTONTOWN, TN
37048

Home Phone: (615) 983-9354

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10992

Stock Desc: 2025 TT FOREST RIVER

ROCKWOOD MINI 2513S

Model: 2513S

Serial #: 4X4TRLB2XSD461344

Chassis #:

Mileage:

Key #: 4500

Req'n #:

License #:

Trim:

Purchase Date: 07 MAR 25

Date In: 03 MAY 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 07 MAR 25

Job #1 - External

DROPPING OFF SATUDRAY MAY 3RD

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CS AFTER THE LAST STORM CUSTOMER NOTICED WATER LEAKING IN FROM UNDER THE MAIN LIVING SLIDE
UNIT HAS CABINET DAMAGE FROM THE WATER LEAK.

CAUSE: WATER TEST DONE ON SLIDE WITH SLIDE IN AND OUT, NO LEAK FOUND FROM SLIDE. LEAK FROM D-SEAL ON COMPARTMENT DOOR(LINE 7). WATER DID ENTER UNIT UNDER SLIDE AND DAMAGED CABINETS IN KITCHEN.

CORRECTION: LEAK WILL BE ADDRESSED ON LINE 7. SEVERAL DAMAGED STILE/CABINETS, COMPLETE BOTTOM. REMOVE AND REPLACE ALL BOTTOM STILE OF KITCHEN SINK CABINET AREA.
LABOR 6.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CS THAT THE SOLAR IS NOT WORKING CHECK AND ADVISE

CAUSE: SOLAR CONTROLLER NOT READING ANY CHARGE. CONTROL HAS 22. VDC FROM SOLAR. NO VOLTAGE READING ON BATTERY LEGGS. TRACED WIRE FROM BATTERY TO 30 A BREAKER 0 VDC FROM SOLAR CONTROL TO BREAKER.

CORRECTION: REPLACE THE BREAKER AND TEST.
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DRAWER ON LEFT AT BOTTOM AS YOU ENTER UNIT IS NOT WORKING CORRECTLY

CAUSE: DRAWER GUIDE IS OFF BY 1/4" NOT ALLOWING DRAWER TO WORK CORRECT.

Customer #: 92565
CAMPBELL, BRET



CORRECTION: REMOVE DRAWER AND GUIDES, ADD SHIM TO ALLOW THE DRAWER TO FIT
CORRECTLY. REINSTALL GUIDE AND DRAWER.
LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: IF LOOKING AT KITCHEN SINK ON BOTTOM LEFT IS NOT WORKING CORRECTLY
SEEMS THEY ARE NOT SPACED CORRECTLY

CAUSE: DRAWER IS ALSO OFF 1/4" NOT ALLOWING DRAWER TO WORK CORRECTLY.

CORRECTION: REMOVE DRAWER AND GUIDES, ADD SHIM, REINSTALL GUIDE AND DRAWER.
LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPARTMENT DOOR ON NDS BELOW MAIN SLIDE LOCK WILL NOT WORK
CUST HAD ISSUES AT THE TIME OF PICK UP WHEN PURCHASED

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: DS COMPARTMENT DOOR HAS HAD WATER STANDING IN IT DIFF TIMES
DOOR SEEMS TO STICK OUT MORE AT THE TOP THEN THE BOTTOM

CAUSE: WATER LEAKING THROUGH GAP IN D-SEAL NEAR LATCH.D-SEAL HAS A GAP AND
ALLOWING WATER TO ENTER THE COMPARTMENT AREA. WATER IS ALSO RUNNING INTO
KITCHEN AREA UNDER SLIDE. (LINE 2)

CORRECTION: REMOVE AND REPLACE D-SEAL ON COMPARTMENT DOOR.
LABOR 1.0

Subtotal for Job #7: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 May 2025

W/O: 25389



Customer #: 92565
CAMPBELL, BRET

