



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25400



WO #: 25400

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11105
Stock Desc: 2025 TT FOREST RIVER
ROCKWOOD SIGN 8263MBR
Model: 8263MBR
Serial #: 4X4TRLF24S1908844
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 05 MAY 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 28 MAY 25
Warr. Date:

Job #1 - Warranty

COMPLAINT: SHOWER SURROUND HAS A GAP ON THE RIGHT SIDE.

CAUSE: NOTED ON DAF

THE INTERIOR WALL THAT THE SURROUND IS ON HAS A WAVE IN IT. THIS IS CAUSING THE SURROUND TO HAVE THE GAP.

CORRECTION: REMOVE ALL CORNER TRIM TO ACCESS THE WALL PANEL, A BRACE NEEDS TO BE ADDED BEHIND THE WALL PANEL SO THE SURROUND WILL FIT CORRECTLY.

LABOR 2.0

Labor

Job #	Description	Hours	Total
1	REPAIRED AND ADDED A BRACE	2.00	330.00

Parts

Part #	Description	Qty	Price	Total
38-1871	PROFLEX SEALANT WHITE 10 OZ GC28127	1.00	12.38	12.38

Subtotal for Job #1: 342.38

Job #2 - Warranty

COMPLAINT: VALANCE AT THE TOP OF THE BATHROOM DOOR OVERLAY IS TORN AND WALL HAS FILLER ON IT.

CAUSE: NOTED ON DAF

CORRECTION: VALANCE OVERLAY NEEDS TRIMMED DOWN, AREA NEEDS TO BE CLEANED.

LABOR .20

Labor

Job #	Description	Hours	Total
2	REPAIR	0.20	33.00

Subtotal for Job #2: 33.00

Job #3 - Warranty

COMPLAINT: BATHROOM CABINET DOOR IS LOOSE AT THE BOTTOM.

CAUSE: SCREW HOLE IS STRIPPED WHERE THE HINGE IS, NOTED ON DAF.

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: REMOVE THE HINGE, FILL HOLE AND REINSTALL HINGE.
LABOR .30

Labor			
Job #	Description	Hours	Total
3	RESECURED HINGE	0.30	49.50
Subtotal for Job #3:			49.50

Job #4 - Warranty

COMPLAINT: CORNER TRIM AT THE BOTTOM IN THE KITCHEN IS DAMAGED AND HAS BLACK MARKS ON THE BOTTOM.

CAUSE: NOTED ON DAF.

CORRECTION: REMOVE AND REINSTALL NEW TRIM.
LABOR .20

Labor			
Job #	Description	Hours	Total
4	REMOVE AND REINSTALL	0.20	33.00
Subtotal for Job #4:			33.00

Job #5 - Warranty

COMPLAINT: FASCIA ON LEFT OF THE LIVING SLIDE IS CROOKED AND STICKS OUT.

CAUSE: NOTED ON DAF.
FASCIA WAS INSTALLED SIDEWAYS

CORRECTION: FILL GAP, COLOR AND BLEND AREA.
LABOR .10

Labor			
Job #	Description	Hours	Total
5	FILL COLOR AND BLEND	0.30	49.50
Subtotal for Job #5:			49.50

Parts Total:	12.38
Labour Total:	495.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	507.38

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 May 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,