

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2287603
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRLF24S1908844
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010C
 ITEM # RLT8263MBR
 DEALER RO # 25400
 CLAIM START DATE 05/05/2025
 CLAIM END DATE 05/28/2025

Labor rate: \$165.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 60-141-24-00-001602 Fiberglass Tub, Shower Surround - Plumbing/Shower, Tub Surround/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-05 12:58:18 :: Complaint: Shower surround has gap on the right side Cause: Noted on DAF, the interior wall that the surround is on, has a wave in it. This is causing the surround to gap. Correction: Remove all corner trim to access the wall panel, a brace needs to be added behind the wall panel, so the surround will fit correctly.

Model#	Dlr Sub Hrs 2.00	Sub Labor Amt \$330.00	
Serial#	Appr Hrs 2.00	Appr Labor Amt \$330.00	

Notes
 authorized to repair.

Part

Line# 1 **Item #** **Description**
 USERPART Proflex sealant, white 10 oz. GC28127

Model #	Serial #	Part tag			
Sub Qty 1.00	Sub Dlr Price \$12.38	Sub Freight	\$0.00		
Appr Qty 1.00	Appr Dlr Price \$12.38	Appr Freight	\$0.00		

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-101-24-00-004685 Stile - Interior/Interior Doors/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-05 13:00:01 :: Complaint: Valance at the top of the bathroom door overlay is torn and wall has filler on it Cause: Noted on DAF Correction: Valance overlay needs trimmed down, area needs to be cleaned

Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$33.00	
Serial#	Appr Hrs 0.20	Appr Labor Amt \$33.00	

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-02-00-003062 Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-05 13:01:08 :: Complaint: Bathroom cabinet door is loose at the bottom Cause: Screw hole is stripped where the hinge is, noted on DAF Correction: Remove the hinge, fill hole, and reinstall hinge

