



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 25401

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11097

Stock Desc: 2025 TT FOREST RIVER

ROCKWOOD ULTRA 2619FK

Model: 2619FK

Serial #: 4X4TRLF20SZ197340

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 05 MAY 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 27 MAY 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: CABINET AT THE RIGHT OF THE ENTRY DOOR IS LOOSE.

CAUSE: NOTED ON DAF.

CORRECTION: RESECURE THE HINGE TO HOLD THE CABINET DOOR SECURE.

LABOR .10

Labor

Job #	Description	Hours	Total
1	TIGHTEN HINGES	0.10	16.50
Subtotal for Job #1:			16.50

Job #2 - Warranty

COMPLAINT: CABINET DOOR TO LEFT OF ENTRY SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILLED, COLOR AND BLEND THE AREA

LABOR .10

Labor

Job #	Description	Hours	Total
2	COLOR MATCHED AND BLENDED	0.30	49.50
Subtotal for Job #2:			49.50

Job #3 - Warranty

COMPLAINT: DRAWER IN KITCHEN LEFT OF ENTRY WILL NOT CLOSE ALL THE WAY.

CAUSE: NOTED ON DAF
DRAWER GUIDE IS FAULTY.

CORRECTION: REMOVE AND REPLACE THE DRAWER GUIDE.

LABOR .20

Labor

Job #	Description	Hours	Total
3	REPLACED DRAWER GUIDE	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

W/O: 25401



Customer #: 47602
TRIAM RV CENTER-EAST
TN,



30187412A 12"BALL BEARING DRAWER GUIDE 1.00 12.55 12.55
W/STOP CAB SIDE

Subtotal for Job #3: 45.55

Job #4 - Warranty

COMPLAINT: VALANCE TO RIGHT OF THE SEATING IS LOOSE AND SIDEWAYS.

CAUSE: NOTED ON DAF.

CORRECTION: RESECURE THE VALANCE IN CORRECT PLACE.

LABOR .10

Labor

Job #	Description	Hours	Total
4	RESECURED IN PLACE	0.10	16.50

Subtotal for Job #4: 16.50

Job #5 - Warranty

COMPLAINT: WINDOW TRIM OVER RECLINERS ARE SCRATCHED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND THE SCRATCHES.

LABOR .20

Labor

Job #	Description	Hours	Total
5	FILL COLOR AND BLEND	0.20	33.00

Subtotal for Job #5: 33.00

Job #6 - Warranty

COMPLAINT: BEDROOM DOOR IS SCRATCHED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREA.

LABOR .20

Labor

Job #	Description	Hours	Total
6	FILL COLOR	0.20	33.00

Subtotal for Job #6: 33.00

Job #7 - Warranty

COMPLAINT: INTERIOR SLIDE FASCIA HAS SERVERAL STAPLE HOLES ON BOTH SIDES OF THE FASCIA.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND SMOOTH AREA.

LABOR .20

Labor

Job #	Description	Hours	Total
7	COLOR FILL AND SMOOTH	0.30	49.50

Subtotal for Job #7: 49.50

W/O: 25401



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



W/O: 25401

Parts Total:	12.55
Labour Total:	231.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	243.55

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 27 May 2025

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

