

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2290294
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRLB20SZ197313
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010D
 ITEM # RLT2606WS
 DEALER RO # 25408
 CLAIM START DATE 05/07/2025
 CLAIM END DATE 05/14/2025

Labor rate: \$165.00

OWNER INFORMATION

CARL HAEHNER
 154 MANOR LN
 Jonesborough, TN 37659
 USA

Retail Date of Purchase 04/19/2025

WARRANTY EXPIRATION DATE

04/19/2026

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-102-24-00-001101 Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/
 Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-07 09:31:30 :: Complaint: Interior fascia on slide out has
 nail/staple holes on the squares Cause: Holes are from the install at factory Correction: Fill, color, and blend the
 area

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$49.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$49.50

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-101-24-00-001076 Hinged Passage Door - Interior/Interior Doors/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-07 09:32:36 :: Complaint: Interior door has a black scratch
 on the door Cause: Noted on DAF Correction: Clean, color, and blend the area

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$33.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$33.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-24-00-001050 Cabinet Stiles - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-07 09:34:36 :: Complaint: Interior cabinet stile has staple
 holes Cause: Noted on DAF Correction: Fill, color, and blend area

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$33.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$33.00

Notes
 Authorized to touch up

Labor

Line# 4 **Operation Code** **Operational Description**
 30-103-24-00-001125 Linoleum - Interior/Flooring/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-05-07 09:35:57 :: Complaint: Wrinkle in the lino flooring in the
 living area Cause: Wrinkle developed in lino flooring Correction: Repair the lino floor to lay flat and correctly. Tech
 will use heat to make pliable, then will have to be rolled.

