



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25408



WO #: 25408

Customer: 76295 - HAEHNER, CARL
Address: 154 MANOR LN
JONESBOROUGH, TN
37659

Home Phone: (423) 328-8595

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11096
Stock Desc: 2025 TT FOREST RIVER
ROCKWOOD ULTRA 2606WS
Model: 2606WS
Serial #: 4X4TRLB20SZ197313
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 19 APR 25
Date In: 07 MAY 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 19 APR 25

Job #1 - Warranty

COMPLAINT: INTERIOR FASCIA ON SLIDE OUT HAS NAIL/.STAPLE HOLES ON THE SQUARES.

CAUSE: HOLES ARE FROM THE INSTALL AT FACTORY.

CORRECTION: FILL, COLOR AND BLEND THE AREA.
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: INTERIOR DOOR HAS A BLACK SCRATCH ON THE DOOR.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THE AREA.
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: INTERIOR CABINET STILE HAS STAPLE HOLES.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREA.
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: WRINKLE IN THE LINO FLOORING IN THE LIVING AREA.

CAUSE: WRINKLE DEVELOPED IN LINO FLOORING.

CORRECTION: REPAIR THE LINO FLOOR TO LAY FLAT AND CORRECTLY. TECH WILL USE HEAT TO MAKE PLIABLE AND THEN AREA WILL HAVE TO BE ROLLED.
LABOR 2.0

Customer #: 76295
HAEHNER, CARL



Subtotal for Job #4: 0.00

W/O: 25408

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 May 2025



Customer Work Order

Customer #: 76295
HAEHNER, CARL

